



802.11be40_5510MHz_RU_26/0_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 11:13:15

802.11be40_5550MHz_RU_26/0_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 11:24:24

802.11be40_5510MHz_RU_26/0_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 11:14:05

802.11be40_5550MHz_RU_26/0_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 11:25:02


802.11be40_5670MHz_RU_26/17_Chain 0




802.11be40_5710MHz_RU_26/17_Chain 0




802.11be40_5670MHz_RU_26/17_Chain 1



802.11be40_5710MHz_RU_26/17_Chain 1




802.11be40_5670MHz_RU_26/17_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 11:41:18

802.11be40_5710MHz_RU_26/17_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 11:45:12

802.11be40_5670MHz_RU_26/17_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 11:41:56

802.11be40_5710MHz_RU_26/17_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 11:46:10

802.11be40_5510MHz_RU_52/37_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:20:53

802.11be40_5550MHz_RU_52/37_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:23:52

802.11be40_5510MHz_RU_52/37_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:21:28

802.11be40_5550MHz_RU_52/37_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:24:30

802.11be40_5510MHz_RU_52/37_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:22:04

802.11be40_5550MHz_RU_52/37_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:25:09

802.11be40_5510MHz_RU_52/37_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:22:54

802.11be40_5550MHz_RU_52/37_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:25:47


802.11be40_5670MHz_RU_52/44_Chain 0




802.11be40_5710MHz_RU_52/44_Chain 0




802.11be40_5670MHz_RU_52/44_Chain 1




802.11be40_5710MHz_RU_52/44_Chain 1




802.11be40_5670MHz_RU_52/44_Chain 2




802.11be40_5710MHz_RU_52/44_Chain 2




802.11be40_5670MHz_RU_52/44_Chain 3



802.11be40_5710MHz_RU_52/44_Chain 3




802.11be40_5510MHz_RU_106/53_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:39:06

802.11be40_5550MHz_RU_106/53_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:43:20

802.11be40_5510MHz_RU_106/53_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:39:53

802.11be40_5550MHz_RU_106/53_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 13:44:11

802.11be40_5510MHz_RU_106/53_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 13:40:37

802.11be40_5550MHz_RU_106/53_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 13:44:49

802.11be40_5510MHz_RU_106/53_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 13:41:24

802.11be40_5550MHz_RU_106/53_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 13:45:31


802.11be40_5670MHz_RU_106/56_Chain 0




802.11be40_5710MHz_RU_106/56_Chain 0




802.11be40_5670MHz_RU_106/56_Chain 1




802.11be40_5710MHz_RU_106/56_Chain 1




802.11be40_5670MHz_RU_106/56_Chain 2




802.11be40_5710MHz_RU_106/56_Chain 2




802.11be40_5670MHz_RU_106/56_Chain 3



802.11be40_5710MHz_RU_106/56_Chain 3




802.11be40_5510MHz_RU_242/61_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:12:57

802.11be40_5550MHz_RU_242/61_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:20:44

802.11be40_5510MHz_RU_242/61_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:13:45

802.11be40_5550MHz_RU_242/61_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:21:33


802.11be40_5510MHz_RU_242/61_Chain 2




802.11be40_5550MHz_RU_242/61_Chain 2




802.11be40_5510MHz_RU_242/61_Chain 3



802.11be40_5550MHz_RU_242/61_Chain 3




802.11be40_5670MHz_RU_242/62_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 14:44:51

802.11be40_5710MHz_RU_242/62_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 14:55:50

802.11be40_5670MHz_RU_242/62_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 14:46:43

802.11be40_5710MHz_RU_242/62_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 14:56:40

802.11be40_5670MHz_RU_242/62_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:53:28

802.11be40_5710MHz_RU_242/62_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:57:20

802.11be40_5670MHz_RU_242/62_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:54:06

802.11be40_5710MHz_RU_242/62_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 14:58:01

802.11be40_5510MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:17:04

802.11be40_5550MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:39:02

802.11be40_5670MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:45:09

802.11be40_5710MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:51:13

802.11be40_5510MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:18:39

802.11be40_5550MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:40:26

802.11be40_5670MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:46:34

802.11be40_5710MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 17.NOV.2025 18:52:59

802.11be40_5510MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 18:20:15

802.11be40_5550MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 18:41:52

802.11be40_5670MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 18:47:46

802.11be40_5710MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 18:54:45


802.11be40_5510MHz_RU_484/65_Chain 3




802.11be40_5550MHz_RU_484/65_Chain 3




802.11be40_5670MHz_RU_484/65_Chain 3




802.11be40_5710MHz_RU_484/65_Chain 3




802.11be80_5530MHz_RU_26/0_Chain 0




802.11be80_5610MHz_RU_26/0_Chain 0




802.11be80_5530MHz_RU_26/0_Chain 1



802.11be80_5610MHz_RU_26/0_Chain 1




802.11be80_5530MHz_RU_26/0_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:04:13

802.11be80_5610MHz_RU_26/0_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:07:58

802.11be80_5530MHz_RU_26/0_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:05:00

802.11be80_5610MHz_RU_26/0_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:08:45

802.11be80_5690MHz_RU_26/36_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:10:26

802.11be80_5690MHz_RU_26/36_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:11:15

802.11be80_5690MHz_RU_26/36_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:11:56

802.11be80_5690MHz_RU_26/36_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:12:46


802.11be80_5530MHz_RU_52/37_Chain 0




802.11be80_5610MHz_RU_52/37_Chain 0




802.11be80_5530MHz_RU_52/37_Chain 1



802.11be80_5610MHz_RU_52/37_Chain 1




802.11be80_5530MHz_RU_52/37_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:18:56

802.11be80_5610MHz_RU_52/37_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:23:19

802.11be80_5530MHz_RU_52/37_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:19:45

802.11be80_5610MHz_RU_52/37_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:24:06


802.11be80_5690MHz_RU_52/52_Chain 0




802.11be80_5690MHz_RU_52/52_Chain 1




802.11be80_5690MHz_RU_52/52_Chain 2



802.11be80_5690MHz_RU_52/52_Chain 3




802.11be80_5530MHz_RU_106/53_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:30:49

802.11be80_5610MHz_RU_106/53_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:34:42

802.11be80_5530MHz_RU_106/53_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:31:42

802.11be80_5610MHz_RU_106/53_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:35:29

802.11be80_5530MHz_RU_106/53_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:32:29

802.11be80_5610MHz_RU_106/53_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:36:18

802.11be80_5530MHz_RU_106/53_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:33:17

802.11be80_5610MHz_RU_106/53_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 15:37:05

802.11be80_5690MHz_RU_106/60_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:47:23

802.11be80_5690MHz_RU_106/60_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:51:30

802.11be80_5690MHz_RU_106/60_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:52:12

802.11be80_5690MHz_RU_106/60_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 15:53:11

802.11be80_5530MHz_RU_242/61_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:12:54

802.11be80_5610MHz_RU_242/61_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:16:29

802.11be80_5530MHz_RU_242/61_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:13:46

802.11be80_5610MHz_RU_242/61_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:17:21

802.11be80_5530MHz_RU_242/61_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:14:36

802.11be80_5610MHz_RU_242/61_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:18:13

802.11be80_5530MHz_RU_242/61_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:15:25

802.11be80_5610MHz_RU_242/61_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:20:33

802.11be80_5690MHz_RU_242/64_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:27:13

802.11be80_5690MHz_RU_242/64_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:28:01

802.11be80_5690MHz_RU_242/64_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:28:46

802.11be80_5690MHz_RU_242/64_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:29:40

802.11be80_5530MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 16:34:55

802.11be80_5610MHz_RU_484/65_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 16:38:35

802.11be80_5530MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 16:35:50

802.11be80_5610MHz_RU_484/65_Chain 1




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
 Date: 19.NOV.2025 16:39:27

802.11be80_5530MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:36:39

802.11be80_5610MHz_RU_484/65_Chain 2




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:40:17

802.11be80_5530MHz_RU_484/65_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:37:29

802.11be80_5610MHz_RU_484/65_Chain 3




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 19.NOV.2025 16:41:17


802.11be80_5690MHz_RU_484/66_Chain 0




802.11be80_5690MHz_RU_484/66_Chain 1




802.11be80_5690MHz_RU_484/66_Chain 2



802.11be80_5690MHz_RU_484/66_Chain 3




802.11be80_5530MHz_RU_996/67_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 19:00:56

802.11be80_5610MHz_RU_996/67_Chain 0




ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 19:07:53

802.11be80_5690MHz_RU_996/67_Chain 0



ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 19:14:48

802.11be80_5530MHz_RU_996/67_Chain 1



ProjectNo.:2509T61338E-RF Tester:Gavy Kim
Date: 17.NOV.2025 19:02:19