



802.11be40_6445MHz_RU_484/65_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:39:44

802.11be40_6485MHz_RU_484/65_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:42:05

802.11be80_6545MHz_RU_996/67_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:14:14

802.11be80_6465MHz_RU_996/67_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:09:13

802.11be80_6545MHz_RU_996/67_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:18:58

802.11be80_6465MHz_RU_996/67_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:21:09

802.11be80_6545MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:13:38

802.11be80_6465MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:10:49

802.11be80_6545MHz_RU_996/67_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:19:06

802.11be80_6465MHz_RU_996/67_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:16:19

802.11be160_6505MHz_RU_2*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:19:05

802.11be160_6505MHz_RU_2*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:24:09

802.11be160_6505MHz_RU_2*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:37:55

802.11be160_6505MHz_RU_2*996_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:41:34

802.11be320_6425MHz_RU_4*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 16:04:12

802.11be320_6425MHz_RU_4*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 22.NOV.2025 09:24:35

802.11be320_6425MHz_RU_4*996_Chain 2



ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 18:10:58


802.11be320_6425MHz_RU_4*996_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 22.NOV.2025 09:21:19

6.8G


802.11be20_6535MHz_RU_242/61_Chain 0




802.11be20_6695MHz_RU_242/61_Chain 0




802.11be20_6855MHz_RU_242/61_Chain 0




802.11be20_6535MHz_RU_242/61_Chain 1




802.11be20_6695MHz_RU_242/61_Chain 1



802.11be20_6855MHz_RU_242/61_Chain 1




802.11be20_6535MHz_RU_242/61_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:59:54

802.11be20_6695MHz_RU_242/61_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 11:18:31

802.11be20_6855MHz_RU_242/61_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 11:23:40

802.11be20_6535MHz_RU_242/61_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 11:27:20

802.11be20_6695MHz_RU_242/61_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 11:30:33

802.11be20_6855MHz_RU_242/61_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 11:33:48

802.11be40_6565MHz_RU_484/65_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:59:51

802.11be40_6685MHz_RU_484/65_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:07:12

802.11be40_6845MHz_RU_484/65_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:10:05

802.11be40_6565MHz_RU_484/65_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:24:37

802.11be40_6685MHz_RU_484/65_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:19:14

802.11be40_6845MHz_RU_484/65_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:16:25

802.11be40_6565MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:40:01

802.11be40_6685MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:43:22

802.11be40_6845MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 00:46:15

802.11be40_6565MHz_RU_484/65_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 17:49:07

802.11be40_6685MHz_RU_484/65_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 17:55:27

802.11be40_6845MHz_RU_484/65_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 18.NOV.2025 18:03:08

802.11be80_6865MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:29:52

802.11be80_6625MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:04:36

802.11be80_6705MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 02:00:57

802.11be80_6785MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:55:41

802.11be80_6865MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:34:37

802.11be80_6625MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:44:24

802.11be80_6705MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:48:18

802.11be80_6785MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:51:32

802.11be80_6865MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:38:48

802.11be80_6625MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:41:16

802.11be80_6705MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:37:48

802.11be80_6785MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:35:14

802.11be80_6865MHz_RU_996/67_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 10:42:23

802.11be80_6625MHz_RU_996/67_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:24:29

802.11be80_6705MHz_RU_996/67_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:28:31

802.11be80_6785MHz_RU_996/67_Chain 3




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:31:59

802.11be160_6825MHz_RU_2*996_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:57:02

802.11be160_6665MHz_RU_2*996_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 20.NOV.2025 14:53:47

802.11be160_6825MHz_RU_2*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:13:35

802.11be160_6665MHz_RU_2*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:10:32

802.11be160_6825MHz_RU_2*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:30:44

802.11be160_6665MHz_RU_2*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:26:53

802.11be160_6825MHz_RU_2*996_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:53:22

802.11be160_6665MHz_RU_2*996_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:50:16

802.11be320_6585MHz_RU_4*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 16:24:10

802.11be320_6745MHz_RU_4*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 16:32:03

802.11be320_6585MHz_RU_4*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 17:31:58

802.11be320_6745MHz_RU_4*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 17:41:31

802.11be320_6585MHz_RU_4*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 18:14:57

802.11be320_6745MHz_RU_4*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 18:22:00

802.11be320_6585MHz_RU_4*996_Chain 3




802.11be320_6745MHz_RU_4*996_Chain 3




7G


802.11be20_6875MHz_RU_242/61_Chain 0




802.11be20_6895MHz_RU_242/61_Chain 0




802.11be20_6995MHz_RU_242/61_Chain 0



802.11be20_7095MHz_RU_242/61_Chain 0




802.11be20_6875MHz_RU_242/61_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 16:15:33

802.11be20_6895MHz_RU_242/61_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 16:19:52

802.11be20_6995MHz_RU_242/61_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 16:59:13

802.11be20_7095MHz_RU_242/61_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 20:31:49

802.11be20_6875MHz_RU_242/61_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 20:41:21

802.11be20_6895MHz_RU_242/61_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 17.NOV.2025 20:46:14

802.11be20_6995MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 20:52:57

802.11be20_7095MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 20:58:52

802.11be20_6875MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 21:03:59

802.11be20_6895MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 21:08:24

802.11be20_6995MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 21:16:22

802.11be20_7095MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 21:21:45

802.11be40_6885MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 14:57:17

802.11be40_6925MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 15:18:07

802.11be40_7005MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 15:32:00

802.11be40_7085MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 15:36:51

802.11be40_6885MHz_RU_484/65_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 15:39:58

802.11be40_6925MHz_RU_484/65_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 15:43:46

802.11be40_7005MHz_RU_484/65_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:05:26

802.11be40_7085MHz_RU_484/65_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:09:49

802.11be40_6885MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:14:28

802.11be40_6925MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:17:01

802.11be40_7005MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:23:00

802.11be40_7085MHz_RU_484/65_Chain 2




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:27:29

802.11be40_6885MHz_RU_484/65_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 16:34:52

802.11be40_6925MHz_RU_484/65_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 18:07:07

802.11be40_7005MHz_RU_484/65_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 18:13:12

802.11be40_7085MHz_RU_484/65_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 19.NOV.2025 18:17:49

802.11be80_6945MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 00:28:56

802.11be80_7025MHz_RU_996/67_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 00:36:03

802.11be80_6945MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 00:50:42

802.11be80_7025MHz_RU_996/67_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 00:44:33

802.11be80_6945MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 00:55:56

802.11be80_7025MHz_RU_996/67_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:02:54

802.11be80_6945MHz_RU_996/67_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:17:17

802.11be80_7025MHz_RU_996/67_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 01:11:13

802.11be160_6985MHz_RU_2*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:00:42

802.11be160_6985MHz_RU_2*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:17:55

802.11be160_6985MHz_RU_2*996_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:34:42

802.11be160_6985MHz_RU_2*996_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 20.NOV.2025 15:56:49

802.11be320_6905MHz_RU_4*996_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 16:39:04

802.11be320_6905MHz_RU_4*996_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 17:49:13

802.11be320_6905MHz_RU_4*996_Chain 2



ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 21.NOV.2025 19:06:15

802.11be320_6905MHz_RU_4*996_Chain 3



ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 22.NOV.2025 09:41:14