




802.11be20_6515MHz_RU_26&106_MRU2_Chain 3




802.11be20_6515MHz_RU_26&52_MRU3_Chain 3




802.11be20_6435MHz_RU_26/0_Chain 0




802.11be20_6475MHz_RU_26/0_Chain 0




802.11be20_6435MHz_RU_26/0_Chain 1



802.11be20_6475MHz_RU_26/0_Chain 1




802.11be20_6435MHz_RU_26/0_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:07:47

802.11be20_6475MHz_RU_26/0_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:11:55

802.11be20_6435MHz_RU_26/0_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:13:46

802.11be20_6475MHz_RU_26/0_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:17:11

802.11be20_6515MHz_RU_26/8_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:55:05

802.11be20_6515MHz_RU_26/8_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:56:14

802.11be20_6515MHz_RU_26/8_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:59:45

802.11be20_6515MHz_RU_26/8_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:00:43

802.11be20_6435MHz_RU_52/37_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:25:53

802.11be20_6475MHz_RU_52/37_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:28:47

802.11be20_6435MHz_RU_52/37_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:34:29

802.11be20_6475MHz_RU_52/37_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:38:59

802.11be20_6435MHz_RU_52/37_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:42:13

802.11be20_6475MHz_RU_52/37_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:43:20

802.11be20_6435MHz_RU_52/37_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:46:37

802.11be20_6475MHz_RU_52/37_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 11:48:25

802.11be20_6515MHz_RU_52/40_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:06:59

802.11be20_6515MHz_RU_52/40_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:08:04


802.11be20_6515MHz_RU_52/40_Chain 2




802.11be20_6515MHz_RU_52/40_Chain 3




802.11be20_6435MHz_RU_106/53_Chain 0




802.11be20_6475MHz_RU_106/53_Chain 0




802.11be20_6435MHz_RU_106/53_Chain 1



802.11be20_6475MHz_RU_106/53_Chain 1




802.11be20_6435MHz_RU_106/53_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:42:48

802.11be20_6475MHz_RU_106/53_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:44:42

802.11be20_6435MHz_RU_106/53_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:49:08

802.11be20_6475MHz_RU_106/53_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 09:50:15

802.11be20_6515MHz_RU_106/54_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:20:04

802.11be20_6515MHz_RU_106/54_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 17.NOV.2025 10:22:29


802.11be20_6515MHz_RU_106/54_Chain 2




802.11be20_6515MHz_RU_106/54_Chain 3




802.11be20_6435MHz_RU_242/61_Chain 0




802.11be20_6475MHz_RU_242/61_Chain 0




802.11be20_6515MHz_RU_242/61_Chain 0



802.11be20_6435MHz_RU_242/61_Chain 1




802.11be20_6475MHz_RU_242/61_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:28:27

802.11be20_6515MHz_RU_242/61_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:32:51

802.11be20_6435MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:37:49

802.11be20_6475MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:40:12

802.11be20_6515MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:45:52

802.11be20_6435MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:47:50

802.11be20_6475MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:50:49

802.11be20_6515MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 15.NOV.2025 10:57:50

802.11be40_6525MHz_RU_26&106_MRU4_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:34:38

802.11be40_6525MHz_RU_26&52_MRU6_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 11:00:58

802.11be40_6445MHz_RU_26&106_MRU1_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 10:24:47

802.11be40_6445MHz_RU_26&52_MRU1_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 09:25:11

802.11be40_6485MHz_RU_26&106_MRU4_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:33:39

802.11be40_6485MHz_RU_26&52_MRU6_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 10:59:37

802.11be40_6525MHz_RU_26&106_MRU4_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:45:47

802.11be40_6525MHz_RU_26&52_MRU6_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 11:52:53

802.11be40_6445MHz_RU_26&106_MRU1_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 10:30:51

802.11be40_6445MHz_RU_26&52_MRU1_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 09:38:03

802.11be40_6485MHz_RU_26&106_MRU4_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:44:48

802.11be40_6485MHz_RU_26&52_MRU6_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 11:51:31

802.11be40_6525MHz_RU_26&106_MRU4_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:54:46

802.11be40_6525MHz_RU_26&52_MRU6_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:09:48

802.11be40_6445MHz_RU_26&106_MRU1_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 10:38:27

802.11be40_6445MHz_RU_26&52_MRU1_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 10:01:10


802.11be40_6485MHz_RU_26&106_MRU4_Chain 2




802.11be40_6485MHz_RU_26&52_MRU6_Chain 2




802.11be40_6525MHz_RU_26&106_MRU4_Chain 3




802.11be40_6525MHz_RU_26&52_MRU6_Chain 3




802.11be40_6445MHz_RU_26&106_MRU1_Chain 3



802.11be40_6445MHz_RU_26&52_MRU1_Chain 3




802.11be40_6485MHz_RU_26&106_MRU4_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 14:05:21

802.11be40_6485MHz_RU_26&52_MRU6_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 5.DEC.2025 13:17:51

802.11be40_6525MHz_RU_26/0_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:30:35

802.11be40_6445MHz_RU_26/0_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:28:02

802.11be40_6525MHz_RU_26/0_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:07:43

802.11be40_6445MHz_RU_26/0_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:05:02

802.11be40_6525MHz_RU_26/0_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:10:33

802.11be40_6445MHz_RU_26/0_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:12:23

802.11be40_6525MHz_RU_26/0_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:24:06

802.11be40_6445MHz_RU_26/0_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:19:13

802.11be40_6485MHz_RU_26/17_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:39:44

802.11be40_6485MHz_RU_26/17_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:33:38

802.11be40_6485MHz_RU_26/17_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:32:06

802.11be40_6485MHz_RU_26/17_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:30:06

802.11be40_6525MHz_RU_52/37_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:12:52

802.11be40_6445MHz_RU_52/37_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:10:35

802.11be40_6525MHz_RU_52/37_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:15:29

802.11be40_6445MHz_RU_52/37_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:18:00

802.11be40_6525MHz_RU_52/37_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 23:14:34

802.11be40_6445MHz_RU_52/37_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:20:08

802.11be40_6525MHz_RU_52/37_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:39:05

802.11be40_6445MHz_RU_52/37_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:36:57

802.11be40_6485MHz_RU_52/44_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 21:04:10

802.11be40_6485MHz_RU_52/44_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:49:15

802.11be40_6485MHz_RU_52/44_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:46:31

802.11be40_6485MHz_RU_52/44_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:43:03

802.11be40_6525MHz_RU_106/53_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:16:15

802.11be40_6445MHz_RU_106/53_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:55:57

802.11be40_6525MHz_RU_106/53_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:13:23

802.11be40_6445MHz_RU_106/53_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:01:28

802.11be40_6525MHz_RU_106/53_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:11:31

802.11be40_6445MHz_RU_106/53_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:03:26

802.11be40_6525MHz_RU_106/53_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:09:39

802.11be40_6445MHz_RU_106/53_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:05:19

802.11be40_6485MHz_RU_106/56_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:25:05

802.11be40_6485MHz_RU_106/56_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:28:27

802.11be40_6485MHz_RU_106/56_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:29:49

802.11be40_6485MHz_RU_106/56_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 20:31:39

802.11be40_6525MHz_RU_242/61_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:29:49

802.11be40_6445MHz_RU_242/61_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:19:00

802.11be40_6525MHz_RU_242/61_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:34:44

802.11be40_6445MHz_RU_242/61_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:38:32

802.11be40_6525MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:46:51

802.11be40_6445MHz_RU_242/61_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:42:37

802.11be40_6525MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 18:17:09

802.11be40_6445MHz_RU_242/61_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 18:14:13

802.11be40_6485MHz_RU_242/62_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:08:15

802.11be40_6485MHz_RU_242/62_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 19:04:13

802.11be40_6485MHz_RU_242/62_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 18:24:43

802.11be40_6485MHz_RU_242/62_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 18:21:44

802.11be40_6525MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 15:43:01

802.11be40_6445MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 15:32:42

802.11be40_6485MHz_RU_484/65_Chain 0




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 15:41:22

802.11be40_6525MHz_RU_484/65_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:24:20

802.11be40_6445MHz_RU_484/65_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 15:57:19

802.11be40_6485MHz_RU_484/65_Chain 1




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:20:50

802.11be40_6525MHz_RU_484/65_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:37:08

802.11be40_6445MHz_RU_484/65_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:26:20

802.11be40_6485MHz_RU_484/65_Chain 2




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:32:46

802.11be40_6525MHz_RU_484/65_Chain 3




ProjectNo.:2504Z00193E-RF Tester:Len Lin
Date: 18.NOV.2025 16:44:45


802.11be40_6445MHz_RU_484/65_Chain 3




802.11be40_6485MHz_RU_484/65_Chain 3




802.11be80_6545MHz_RU_242&484_MRU1_Chain 0




802.11be80_6545MHz_RU_26&106_MRU8_Chain 0




802.11be80_6545MHz_RU_26&52_MRU11_Chain 0



802.11be80_6465MHz_RU_242&484_MRU4_Chain 0




802.11be80_6465MHz_RU_26&106_MRU1_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 21:26:14

802.11be80_6465MHz_RU_26&52_MRU2_Chain 0




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 20:24:22

802.11be80_6545MHz_RU_242&484_MRU1_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 23:46:24

802.11be80_6545MHz_RU_26&106_MRU8_Chain 1




ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 23:18:05

802.11be80_6545MHz_RU_26&52_MRU11_Chain 1



ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 23:00:08

802.11be80_6465MHz_RU_242&484_MRU4_Chain 1



ProjectNo.:2504200193E-RF Tester:Len Lin
Date: 5.DEC.2025 21:57:57