



Annex to Test Report

For:
Rivian Automotive, LLC

Marketing Name:
Radio Farm (RFM)

Model Name:
RFM1.0

Product Description:
Radio Farm (RFM)

FCC ID: contains 2AW3A-MRN932N & 2AW3A-MRW962B

ISED: contains 26958-MRN932N & 26958-MRW962B

REPORT #: EMC_RIVIA_100_25001_FCC22_24_27_90

DATE: 2025-12-02

CETECOM Inc.

411 Dixon Landing Road ♦ Milpitas, CA 95035 ♦ U.S.A.

Phone: + 1 (408) 586 6200 ♦ Fax: + 1 (408) 586 6299 ♦ E-mail: contact@cetecom.com ♦ <http://www.cetecom.com>

CETECOM Inc. is a Delaware Corporation with Corporation number: 2905571

TABLE OF CONTENTS

1

SETUP PHOTOS.....

3

2

REVISION HISTORY

6

1 Setup Photos

Radiated emission 9 kHz – 30 MHz



Radiated emission 30 MHz – 1 GHz



Radiated emission 1 GHz – 7 GHz



Radiated emission 7 GHz – 18 GHz



Radiated emission 18 GHz – 40 GHz



Test Report #: EMC_RIVIA_100_25001_FCC22_24_27_90_Setup_Photos

FCC ID: contains 2AW3A-MRN932N &
2AW3A-MRW962B

Date of Report 2025-12-02

Page 6 of 6

ISED: contains 26958-MRN932N & 26958-
MRW962B



2 Revision History

Date	Report name	Changes to report	Prepared by
2025-12-02	EMC_RIVIA_100_25001_FCC22_24_27_90 _Setup_Photos	Initial version	Guangcheng Huang

<<< The End >>>