

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs




Figure 1 – Front Face 0mm



Figure 2 – Rear Face 0mm

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs



Figure 3 – Left Side 0mm



Figure 4 – Right Side 0mm

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs



Figure 5 – Top Side 0mm



Figure 6 – Bottom Side 0mm