

Permissive Change Letter

Amazon.com Services LLC

410 Terry Ave N, Seattle, Washington 98109, United States Of America

Date:15 June, 2021

Federal Communications Commission

7435 Oakland Mills Road Columbia MD 21046 USA

Innovation, Science and Economic Development Canada

Spectrum Management Operations Branch 235 Queen Street Ottawa, Ontario K1A 0H5

To Whom It May Concern:

Request for Class II Permissive Changes:

FCC ID: 2AWCC-5677, JAB Date of Grant: March 30, 2021, DTS date of Grant: February 02, 2021

IC: 24273-5677, Issued date: February 3, 2021

Pursuant to CFR 2.1043 and RSP 100 section 7, Amazon.com Services LLC Hereby requests a Class II Permissive Changes (C2PC).

Modification:

1. This version of ZL-ODIN-V1 based on the previous version, the PCB layout of product (power management board and control board) with minor changed, the purpose is make the product more stable and reliable, and the other not changed, detail refer to Circuit diagram and PCB layout.
2. There is no change in hardware or in existing RF relevant portion of the Bluetooth unit and License radio module.
3. No change in wireless technologies and configuration;
4. Firmware cannot be modified by end-user;

Thank you,

By

:

DocuSigned by:
Rick Ratley
4D87468A4772460...

(Signature)

Rick Ratley

(Print Name)

Title

:

Authorized Signatory

Telephone

:

(650) 426-1100

On behalf of

:

Amazon.com Services LLC

(Company Name)