

Permissive Change Letter

Amazon.com Services LLC

410 Terry Ave N, Seattle, Washington 98109, United States Of America

Date: 18 March, 2021

Federal Communications Commission

7435 Oakland Mills Road Columbia MD 21046 USA

Innovation, Science and Economic Development Canada

Spectrum Management Operations Branch 235 Queen Street Ottawa, Ontario K1A 0H5

To Whom It May Concern:

Request for Class II Permissive Changes:

FCC ID: 2AWCC-5677, Date of Grant: 02/02/2021

IC: 24273-5677, Issued date: February 3, 2021

Pursuant to CFR 2.1043 and RSP 100 section 7, Amazon.com Services LLC Hereby requests a Class II Permissive Changes (C2PC).

Modification:

1. Based on the previous version adding a LED light bar for illumination purpose.
2. Based on the previous version adding an AC/DC converter for LED light bar (This locker can be use alternative power by internal battery or AC/DC converter).
3. There is no change in hardware or in existing RF relevant portion of the Bluetooth unit and License radio module.
4. No change in wireless technologies and configuration;
5. Firmware cannot be modified by end-user;

Thank you,

By

□ □

Rick Ratley

-4D87468A4772460...

(Print Name)

■ ■

Telephone

□
□

■ ■

Amazon.com Services LLC

(Company Name)