



CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1857.5 CC2:1872.5MHz_CC1: 75@0 CC2: 75@0




CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1872.5 CC2:1887.5MHz_CC1: 75@0 CC2: 75@0






Report No.: SUCR260400031709
Page: 74 of 550

CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1887.5 CC2:1902.5MHz_CC1: 75@0 CC2: 75@0




CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1857.5 CC2:1872.5MHz_CC1: 75@0 CC2: 75@0






Report No.: SUCR260400031709
Page: 76 of 550

CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1872.5 CC2:1887.5MHz_CC1: 75@0 CC2:
75@0




CA_2C_SISO_NTNV_CC1:15 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1887.5 CC2:1902.5MHz_CC1: 75@0 CC2:
75@0






Report No.: SUCR260400031709
Page: 78 of 550


CA_2C_SISO_NTNV_CC1:15_CC2:20MHz_CC1:QPSK_CC2:QPSK_CC1:1857.5_CC2:1874.6MHz_CC1: 75@0_CC2: 100@0




CA_2C_SISO_NTNV_CC1:15_CC2:20MHz_CC1:QPSK_CC2:QPSK_CC1:1870.2_CC2:1887.3MHz_CC1: 75@0_CC2: 100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:QPSK CC2:QPSK CC1:1882.9 CC2:1900MHz_CC1: 75@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1857.5 CC2:1874.6MHz_CC1: 75@0 CC2: 100@0



CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1870.2 CC2:1887.3MHz_CC1: 75@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1882.9 CC2:1900MHz_CC1: 75@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 82 of 550

CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1857.5 CC2:1874.6MHz_CC1: 75@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1870.2 CC2:1887.3MHz_CC1: 75@0 CC2: 100@0






Report No.: SUCR260400031709
Page: 84 of 550

CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1882.9 CC2:1900MHz_CC1: 75@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1857.5 CC2:1874.6MHz_CC1: 75@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 86 of 550

CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1870.2 CC2:1887.3MHz_CC1: 75@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:15 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1882.9 CC2:1900MHz_CC1: 75@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 88 of 550


CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:1860 CC2:1871.7MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK_CC1:1877.9 CC2:1889.6MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:QPSK CC2:QPSK CC1:1895.8 CC2:1907.5MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:1860 CC2:1871.7MHz_CC1: 100@0 CC2: 25@0



CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:1877.9 CC2:1889.6MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:16QAM CC2:16QAM_CC1:1895.8 CC2:1907.5MHz_CC1: 100@0 CC2: 25@0






Report No.: SUCR260400031709
Page: 92 of 550


CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:1860 CC2:1871.7MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:1877.9 CC2:1889.6MHz_CC1: 100@0 CC2: 25@0



CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:64QAM CC2:64QAM_CC1:1895.8 CC2:1907.5MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:256QAM CC2:256QAM_CC1:1860 CC2:1871.7MHz_CC1: 100@0 CC2: 25@0






Report No.: SUCR260400031709
Page: 95 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:256QAM CC2:256QAM_CC1:1877.9 CC2:1889.6MHz_CC1: 100@0 CC2: 25@0




CA_2C_SISO_NTNV_CC1:20 CC2:5MHz_CC1:256QAM CC2:256QAM_CC1:1895.8 CC2:1907.5MHz_CC1: 100@0 CC2: 25@0






Report No.: SUCR260400031709
Page: 97 of 550


CA_2C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:1860_CC2:1874.4MHz_CC1: 100@0_CC2: 50@0




CA_2C_SISO_NTNV_CC1:20_CC2:10MHz_CC1:QPSK_CC2:QPSK_CC1:1875.3_CC2:1889.7MHz_CC1: 100@0_CC2: 50@0




CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:QPSK CC2:QPSK CC1:1890.6 CC2:1905MHz_CC1: 100@0 CC2: 50@0




CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:1860 CC2:1874.4MHz_CC1: 100@0 CC2: 50@0



CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:1875.3 CC2:1889.7MHz_CC1: 100@0 CC2:
50@0




CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:16QAM CC2:16QAM_CC1:1890.6 CC2:1905MHz_CC1: 100@0 CC2:
50@0






Report No.: SUCR260400031709
Page: 101 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:1860 CC2:1874.4MHz_CC1: 100@0 CC2:
50@0




CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:1875.3 CC2:1889.7MHz_CC1: 100@0 CC2:
50@0





Report No.: SUCR260400031709
Page: 103 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:64QAM CC2:64QAM_CC1:1890.6 CC2:1905MHz_CC1: 100@0 CC2:
50@0



CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:256QAM CC2:256QAM_CC1:1860 CC2:1874.4MHz_CC1: 100@0 CC2:
50@0

