





Report No.: SUCR260400031709
Page: 105 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:256QAM CC2:256QAM_CC1:1875.3 CC2:1889.7MHz_CC1: 100@0 CC2: 50@0




CA_2C_SISO_NTNV_CC1:20 CC2:10MHz_CC1:256QAM CC2:256QAM_CC1:1890.6 CC2:1905MHz_CC1: 100@0 CC2: 50@0






Report No.: SUCR260400031709
Page: 107 of 550


CA_2C_SISO_NTNV_CC1:20_CC2:15MHz_CC1:QPSK_CC2:QPSK_CC1:1860_CC2:1877.1MHz_CC1: 100@0_CC2: 75@0




CA_2C_SISO_NTNV_CC1:20_CC2:15MHz_CC1:QPSK_CC2:QPSK_CC1:1872.7_CC2:1889.8MHz_CC1: 100@0_CC2: 75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz CC1:QPSK CC2:QPSK_CC1:1885.4 CC2:1902.5MHz CC1: 100@0 CC2: 75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:1860 CC2:1877.1MHz_CC1: 100@0 CC2: 75@0



CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:1872.7 CC2:1889.8MHz_CC1: 100@0 CC2: 75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:16QAM CC2:16QAM_CC1:1885.4 CC2:1902.5MHz_CC1: 100@0 CC2: 75@0






Report No.: SUCR260400031709
Page: 111 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1860 CC2:1877.1MHz_CC1: 100@0 CC2:
75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1872.7 CC2:1889.8MHz_CC1: 100@0 CC2:
75@0






Report No.: SUCR260400031709
Page: 113 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:64QAM CC2:64QAM_CC1:1885.4 CC2:1902.5MHz_CC1: 100@0 CC2:
75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1860 CC2:1877.1MHz_CC1: 100@0 CC2:
75@0






Report No.: SUCR260400031709
Page: 115 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1872.7 CC2:1889.8MHz_CC1: 100@0 CC2: 75@0




CA_2C_SISO_NTNV_CC1:20 CC2:15MHz_CC1:256QAM CC2:256QAM_CC1:1885.4 CC2:1902.5MHz_CC1: 100@0 CC2: 75@0






Report No.: SUCR260400031709
Page: 117 of 550


CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:1860 CC2:1879.8MHz_CC1: 100@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:1870.1 CC2:1889.9MHz_CC1: 100@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:1880.2 CC2:1900MHz_CC1: 100@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1860 CC2:1879.8MHz_CC1: 100@0 CC2: 100@0



CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1870.1 CC2:1889.9MHz_CC1: 100@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1880.2 CC2:1900MHz_CC1: 100@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 121 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1860 CC2:1879.8MHz_CC1: 100@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1870.1 CC2:1889.9MHz_CC1: 100@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 123 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1880.2 CC2:1900MHz_CC1: 100@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1860 CC2:1879.8MHz_CC1: 100@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 125 of 550

CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1870.1 CC2:1889.9MHz_CC1: 100@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:20 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1880.2 CC2:1900MHz_CC1: 100@0 CC2: 100@0







Report No.: SUCR260400031709
Page: 127 of 550

2.2.2 CA_2C_NTNV_XDB







CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:QPSK CC2:QPSK_CC1:1888.3 CC2:1900MHz_CC1: 25@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1852.5 CC2:1864.2MHz_CC1: 25@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1870.4 CC2:1882.1MHz_CC1: 25@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:16QAM CC2:16QAM_CC1:1888.3 CC2:1900MHz_CC1: 25@0 CC2: 100@0



CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1852.5 CC2:1864.2MHz_CC1: 25@0 CC2:
100@0




CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1870.4 CC2:1882.1MHz_CC1: 25@0 CC2:
100@0






Report No.: SUCR260400031709
Page: 133 of 550


CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:64QAM CC2:64QAM_CC1:1888.3 CC2:1900MHz_CC1: 25@0 CC2: 100@0




CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1852.5 CC2:1864.2MHz_CC1: 25@0 CC2: 100@0



CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1870.4 CC2:1882.1MHz_CC1: 25@0 CC2: 100@0



CA_2C_SISO_NTNV_CC1:5 CC2:20MHz_CC1:256QAM CC2:256QAM_CC1:1888.3 CC2:1900MHz_CC1: 25@0 CC2: 100@0





Report No.: SUCR260400031709
Page: 136 of 550