





































































Report No. : EP031609-03



WWAN Module 1

Model Name: EM9190

