




Annex B

Internal Photos

Report No.: HK2007061941-E

Page 1 of 5





BT
Antenna

