






Date: 18.MAR.2026 11:07:00

Band41(2535-2655)-5MHz-16QAM-41215-1RB#24-0.009~0.15-PASS




Date: 18.MAR.2026 11:08:07

Band41(2535-2655)-5MHz-16QAM-41215-1RB#24-0.15~30-PASS




Date: 18.MAR.2026 11:08:24


Band41(2535-2655)-5MHz-16QAM-41215-1RB#24-30~1000-PASS




Date: 18.MAR.2026 11:08:41

Band41(2535-2655)-5MHz-16QAM-41215-1RB#24-1000~20000-PASS






Date: 18.MAR.2026 11:14:18




Date: 18.MAR.2026 11:14:37

Band41(2535-2655)-5MHz-16QAM-41215-25RB#0-1000~20000-PASS




Date: 18.MAR.2026 11:53:01

Band41(2535-2655)-10MHz-QPSK-40090-1RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 11:54:08

Band41(2535-2655)-10MHz-QPSK-40090-1RB#0-0.15~30-PASS




Date: 18.MAR.2026 11:54:25




Date: 18.MAR.2026 11:54:42

Band41(2535-2655)-10MHz-QPSK-40090-1RB#0-30~1000-PASS



Date: 18.MAR.2026 11:55:01


Band41(2535-2655)-10MHz-QPSK-40090-1RB#0-1000~20000-PASS




Date: 18.MAR.2026 12:30:29

Band41(2535-2655)-10MHz-QPSK-40090-1RB#0-20000~27000-PASS


Band41(2535-2655)-10MHz-QPSK-40090-1RB#49-0.009~0.15-PASS






Date: 18.MAR.2026 12:36:22

Band41(2535-2655)-10MHz-QPSK-40090-50RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 12:37:31

Band41(2535-2655)-10MHz-QPSK-40090-50RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:37:48

Band41(2535-2655)-10MHz-QPSK-40090-50RB#0-30~1000-PASS




Date: 18.MAR.2026 12:38:06

Band41(2535-2655)-10MHz-QPSK-40090-50RB#0-1000~20000-PASS




Date: 18.MAR.2026 12:38:27

Band41(2535-2655)-10MHz-QPSK-40090-50RB#0-20000~27000-PASS




Date: 18.MAR.2026 12:27:37

Band41(2535-2655)-10MHz-16QAM-40090-1RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 12:28:44

Band41(2535-2655)-10MHz-16QAM-40090-1RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:29:04




Date: 18.MAR.2026 12:29:21

Band41(2535-2655)-10MHz-16QAM-40090-1RB#0-30~1000-PASS

Band41(2535-2655)-10MHz-16QAM-40090-1RB#0-1000~20000-PASS




Date: 18.MAR.2026 12:29:39



Date: 18.MAR.2026 12:33:20


Band41(2535-2655)-10MHz-16QAM-40090-1RB#0-20000~27000-PASS

Band41(2535-2655)-10MHz-16QAM-40090-1RB#49-0.009~0.15-PASS




Date: 18.MAR.2026 12:34:29

Band41(2535-2655)-10MHz-16QAM-40090-1RB#49-0.15~30-PASS




Date: 18.MAR.2026 12:34:49

Band41(2535-2655)-10MHz-16QAM-40090-1RB#49-30~1000-PASS




Date: 18.MAR.2026 12:35:08

Band41(2535-2655)-10MHz-16QAM-40090-1RB#49-1000~20000-PASS




Date: 18.MAR.2026 12:35:30

Band41(2535-2655)-10MHz-16QAM-40090-1RB#49-20000~27000-PASS




Date: 18.MAR.2026 12:46:21

Band41(2535-2655)-10MHz-16QAM-40090-50RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 12:47:30

Band41(2535-2655)-10MHz-16QAM-40090-50RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:47:50

Band41(2535-2655)-10MHz-16QAM-40090-50RB#0-30~1000-PASS




Date: 18.MAR.2026 12:48:07




Date: 18.MAR.2026 12:48:26

Band41(2535-2655)-10MHz-16QAM-40090-50RB#0-1000~20000-PASS



Date: 18.MAR.2026 12:49:18


Band41(2535-2655)-10MHz-16QAM-40090-50RB#0-20000~27000-PASS




Date: 18.MAR.2026 12:49:55

Band41(2535-2655)-10MHz-QPSK-40590-1RB#0-0.009~0.15-PASS

Band41(2535-2655)-10MHz-QPSK-40590-1RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:50:12




Date: 18.MAR.2026 12:50:29

Band41(2535-2655)-10MHz-QPSK-40590-1RB#0-30~1000-PASS





Date: 18.MAR.2026 12:50:47

Band41(2535-2655)-10MHz-QPSK-40590-1RB#0-20000~27000-PASS





Date: 18.MAR.2026 12:54:54

Band41(2535-2655)-10MHz-QPSK-40590-1RB#49-0.009~0.15-PASS




Band41(2535-2655)-10MHz-QPSK-40590-1RB#49-0.15~30-PASS

Band41(2535-2655)-10MHz-QPSK-40590-1RB#49-30~1000-PASS




Band41(2535-2655)-10MHz-QPSK-40590-1RB#49-1000~20000-PASS

Band41(2535-2655)-10MHz-QPSK-40590-1RB#49-20000~27000-PASS




Date: 18.MAR.2026 12:59:20

Band41(2535-2655)-10MHz-QPSK-40590-50RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 12:59:40

Band41(2535-2655)-10MHz-QPSK-40590-50RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:59:57

Band41(2535-2655)-10MHz-QPSK-40590-50RB#0-30~1000-PASS




Date: 18.MAR.2026 13:00:14

Band41(2535-2655)-10MHz-QPSK-40590-50RB#0-1000~20000-PASS




Date: 18.MAR.2026 13:00:33

Band41(2535-2655)-10MHz-QPSK-40590-50RB#0-20000~27000-PASS




Date: 18.MAR.2026 12:52:06

Band41(2535-2655)-10MHz-16QAM-40590-1RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 12:52:39

Band41(2535-2655)-10MHz-16QAM-40590-1RB#0-0.15~30-PASS




Date: 18.MAR.2026 12:53:37

Band41(2535-2655)-10MHz-16QAM-40590-1RB#0-30~1000-PASS




Date: 18.MAR.2026 12:53:54

Band41(2535-2655)-10MHz-16QAM-40590-1RB#0-1000~20000-PASS




Date: 18.MAR.2026 12:54:04

Band41(2535-2655)-10MHz-16QAM-40590-1RB#0-20000~27000-PASS




Date: 18.MAR.2026 12:57:22

Band41(2535-2655)-10MHz-16QAM-40590-1RB#49-0.009~0.15-PASS




Date: 18.MAR.2026 12:57:46

Band41(2535-2655)-10MHz-16QAM-40590-1RB#49-0.15~30-PASS




Date: 18.MAR.2026 12:58:03

Band41(2535-2655)-10MHz-16QAM-40590-1RB#49-30~1000-PASS




Date: 18.MAR.2026 12:58:21

Band41(2535-2655)-10MHz-16QAM-40590-1RB#49-1000~20000-PASS




Date: 18.MAR.2026 12:58:30

Band41(2535-2655)-10MHz-16QAM-40590-1RB#49-20000~27000-PASS




Date: 18.MAR.2026 13:03:43

Band41(2535-2655)-10MHz-16QAM-40590-50RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 13:04:26

Band41(2535-2655)-10MHz-16QAM-40590-50RB#0-0.15~30-PASS




Date: 18.MAR.2026 13:04:43

Band41(2535-2655)-10MHz-16QAM-40590-50RB#0-30~1000-PASS




Date: 18.MAR.2026 13:05:03

Band41(2535-2655)-10MHz-16QAM-40590-50RB#0-1000~20000-PASS




Date: 18.MAR.2026 13:05:13


Band41(2535-2655)-10MHz-16QAM-40590-50RB#0-20000~27000-PASS



Date: 18.MAR.2026 13:06:05


Band41(2535-2655)-10MHz-QPSK-41190-1RB#0-0.009~0.15-PASS






Date: 18.MAR.2026 13:11:18

Band41(2535-2655)-10MHz-QPSK-41190-1RB#49-0.009~0.15-PASS




Date: 18.MAR.2026 13:12:09

Band41(2535-2655)-10MHz-QPSK-41190-1RB#49-0.15~30-PASS




Date: 18.MAR.2026 13:12:29


Band41(2535-2655)-10MHz-QPSK-41190-1RB#49-30~1000-PASS




Date: 18.MAR.2026 13:12:46

Band41(2535-2655)-10MHz-QPSK-41190-1RB#49-1000~20000-PASS









Date: 18.MAR.2026 13:10:01

Band41(2535-2655)-10MHz-16QAM-41190-1RB#0-30~1000-PASS




Date: 18.MAR.2026 13:10:18

Band41(2535-2655)-10MHz-16QAM-41190-1RB#0-1000~20000-PASS




Date: 18.MAR.2026 13:10:28

Band41(2535-2655)-10MHz-16QAM-41190-1RB#0-20000~27000-PASS




Date: 18.MAR.2026 13:13:57


Band41(2535-2655)-10MHz-16QAM-41190-1RB#49-0.009~0.15-PASS




Band41(2535-2655)-10MHz-16QAM-41190-1RB#49-0.15~30-PASS




Band41(2535-2655)-10MHz-16QAM-41190-1RB#49-30~1000-PASS



Band41(2535-2655)-10MHz-16QAM-41190-1RB#49-1000~20000-PASS




Band41(2535-2655)-10MHz-16QAM-41190-1RB#49-20000~27000-PASS




Date: 18.MAR.2026 13:18:50

Band41(2535-2655)-10MHz-16QAM-41190-50RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 13:19:50

Band41(2535-2655)-10MHz-16QAM-41190-50RB#0-0.15~30-PASS




Date: 18.MAR.2026 13:20:07

Band41(2535-2655)-10MHz-16QAM-41190-50RB#0-30~1000-PASS




Date: 18.MAR.2026 13:20:24

Band41(2535-2655)-10MHz-16QAM-41190-50RB#0-1000~20000-PASS




Date: 18.MAR.2026 13:20:43

Band41(2535-2655)-10MHz-16QAM-41190-50RB#0-20000~27000-PASS




Date: 18.MAR.2026 13:41:34

Band41(2535-2655)-15MHz-QPSK-40115-1RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 13:42:40

Band41(2535-2655)-15MHz-QPSK-40115-1RB#0-0.15~30-PASS




Date: 18.MAR.2026 13:42:57




Date: 18.MAR.2026 13:43:18

Band41(2535-2655)-15MHz-QPSK-40115-1RB#0-30~1000-PASS



Date: 18.MAR.2026 13:43:40


Band41(2535-2655)-15MHz-QPSK-40115-1RB#0-1000~20000-PASS




Date: 18.MAR.2026 13:47:21

Band41(2535-2655)-15MHz-QPSK-40115-1RB#0-20000~27000-PASS


Band41(2535-2655)-15MHz-QPSK-40115-1RB#74-0.009~0.15-PASS






Date: 18.MAR.2026 13:44:32

Band41(2535-2655)-15MHz-16QAM-40115-1RB#0-0.009~0.15-PASS




Date: 18.MAR.2026 13:45:39

Band41(2535-2655)-15MHz-16QAM-40115-1RB#0-0.15~30-PASS



Date: 18.MAR.2026 13:45:56

Band41(2535-2655)-15MHz-16QAM-40115-1RB#0-30~1000-PASS



Date: 18.MAR.2026 13:46:13

Band41(2535-2655)-15MHz-16QAM-40115-1RB#0-1000~20000-PASS