






Date: 2.JUL.2024 22:23:27

Band2_1.4MHz_16QAM_19193_1RB#0_1000~3000_1000~3000




Date: 2.JUL.2024 22:23:42

Band2_1.4MHz_16QAM_19193_1RB#0_3000~20000_3000~20000




Date: 2.JUL.2024 22:23:53

Band2_1.4MHz_QPSK_19193_1RB#5_0.009~0.15_0.009~0.15




Date: 2.JUL.2024 22:24:08

Band2_1.4MHz_QPSK_19193_1RB#5_0.15~30_0.15~30




Date: 2.JUL.2024 22:24:22

Band2_1.4MHz_QPSK_19193_1RB#5_30~1000_30~1000




Date: 2.JUL.2024 22:24:35

Band2_1.4MHz_QPSK_19193_1RB#5_1000~300_0_1000~3000




Date: 2.JUL.2024 22:24:50

Band2_1.4MHz_QPSK_19193_1RB#5_3000~200_00_3000~20000



Date: 2.JUL.2024 22:24:59

Band2_1.4MHz_16QAM_19193_1RB#5_0.009~0.15_0.009~0.15




Date: 2.JUL.2024 22:25:14

Date: 2.JUL.2024 22:25:27

Band2_1.4MHz_16QAM_19193_1RB#5_0.15~30
_0.15~30

Band2_1.4MHz_16QAM_19193_1RB#5_30~1000
_30~1000




Date: 2.JUL.2024 22:25:41

Date: 2.JUL.2024 22:25:56


Band2_1.4MHz_16QAM_19193_1RB#5_1000~3
000_1000~3000

Band2_1.4MHz_16QAM_19193_1RB#5_3000~20
000_3000~20000




Date: 2.JUL.2024 22:26:07

Band2_1.4MHz_QPSK_19193_6RB#0_0.009~0.15_5_0.009~0.15




Date: 2.JUL.2024 22:26:22

Band2_1.4MHz_QPSK_19193_6RB#0_0.15~30_0.15~30




Date: 2.JUL.2024 22:26:35

Band2_1.4MHz_QPSK_19193_6RB#0_30~1000_30~1000



Date: 2.JUL.2024 22:26:49


Band2_1.4MHz_QPSK_19193_6RB#0_1000~3000_0_1000~3000



Date: 2.JUL.2024 22:27:04

Date: 2.JUL.2024 22:27:12


Band2_1.4MHz_QPSK_19193_6RB#0_3000~20000_3000~20000	Band2_1.4MHz_16QAM_19193_6RB#0_0.009~0.15_0.009~0.15
---	--



Date: 2.JUL.2024 22:27:27


Date: 2.JUL.2024 22:27:41

Band2_1.4MHz_16QAM_19193_6RB#0_0.15~30_0.15~30	Band2_1.4MHz_16QAM_19193_6RB#0_30~1000_30~1000
--	--




Date: 2.JUL.2024 22:27:54

Band2_1.4MHz_16QAM_19193_6RB#0_1000~3000_1000~3000




Date: 2.JUL.2024 22:28:09

Band2_1.4MHz_16QAM_19193_6RB#0_3000~20000_3000~20000




Date: 2.JUL.2024 23:00:34

Band2_3MHz_QPSK_18615_1RB#0_0.009~0.15_0.009~0.15




Date: 2.JUL.2024 23:00:49

Band2_3MHz_QPSK_18615_1RB#0_0.15~30.15~30




Date: 2.JUL.2024 23:01:22

Band2_3MHz_QPSK_18615_1RB#0_30~1000_3
0~1000




Date: 2.JUL.2024 23:01:16

Band2_3MHz_QPSK_18615_1RB#0_1000~3000_
1000~3000




Date: 2.JUL.2024 23:01:31

Band2_3MHz_QPSK_18615_1RB#0_3000~2000_
0_3000~20000



Date: 2.JUL.2024 23:01:40


Band2_3MHz_16QAM_18615_1RB#0_0.009~0.15_
_0.009~0.15



Date: 2.JUL.2024 23:01:55

Date: 2.JUL.2024 23:02:09


Band2_3MHz_16QAM_18615_1RB#0_0.15~30_0.15~30	Band2_3MHz_16QAM_18615_1RB#0_30~1000_30~1000
--	--



Date: 2.JUL.2024 23:02:23


Date: 2.JUL.2024 23:02:37

Band2_3MHz_16QAM_18615_1RB#0_1000~3000_1000~3000	Band2_3MHz_16QAM_18615_1RB#0_3000~20000_3000~20000
--	--




Date: 2.JUL.2024 23:02:48

Band2_3MHz_QPSK_18615_1RB#14_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:03:03

Band2_3MHz_QPSK_18615_1RB#14_0.15~30_0.
15~30




Date: 2.JUL.2024 23:03:17

Band2_3MHz_QPSK_18615_1RB#14_30~1000_
30~1000



Date: 2.JUL.2024 23:03:30


Band2_3MHz_QPSK_18615_1RB#14_1000~3000
_1000~3000



Date: 2.JUL.2024 23:03:45

Date: 2.JUL.2024 23:03:55


Band2_3MHz_QPSK_18615_1RB#14_3000~20000_3000~20000	Band2_3MHz_16QAM_18615_1RB#14_0.009~0.15_0.009~0.15
--	---



Date: 2.JUL.2024 23:04:10


Date: 2.JUL.2024 23:04:24

Band2_3MHz_16QAM_18615_1RB#14_0.15~30_0.15~30	Band2_3MHz_16QAM_18615_1RB#14_30~1000_30~1000
---	---




Date: 2.JUL.2024 23:04:37

Band2_3MHz_16QAM_18615_1RB#14_1000~3000_00_1000~3000




Date: 2.JUL.2024 23:04:52

Band2_3MHz_16QAM_18615_1RB#14_3000~20000_00_3000~20000




Date: 2.JUL.2024 23:05:03

Band2_3MHz_QPSK_18615_15RB#0_0.009~0.15_5_0.009~0.15



Date: 2.JUL.2024 23:05:18


Band2_3MHz_QPSK_18615_15RB#0_0.15~30_0.15~30_15~30



Date: 2.JUL.2024 23:05:33

Date: 2.JUL.2024 23:05:46


Band2_3MHz_QPSK_18615_15RB#0_30~1000_30~1000	Band2_3MHz_QPSK_18615_15RB#0_1000~3000_1000~3000
--	--



Date: 2.JUL.2024 23:06:01


Date: 2.JUL.2024 23:06:11

Band2_3MHz_QPSK_18615_15RB#0_3000~20000_3000~20000	Band2_3MHz_16QAM_18615_15RB#0_0.009~0.15_0.009~0.15
--	---




Date: 2.JUL.2024 23:06:26

Band2_3MHz_16QAM_18615_15RB#0_0.15~30_0.15~30




Date: 2.JUL.2024 23:06:39

Band2_3MHz_16QAM_18615_15RB#0_30~1000_30~1000




Date: 2.JUL.2024 23:06:53

Band2_3MHz_16QAM_18615_15RB#0_1000~30_00_1000~3000




Date: 2.JUL.2024 23:07:08

Band2_3MHz_16QAM_18615_15RB#0_3000~200_00_3000~20000




Date: 2.JUL.2024 23:07:20

Band2_3MHz_QPSK_18900_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:07:35

Band2_3MHz_QPSK_18900_1RB#0_0.15~30_0.1
5~30




Date: 2.JUL.2024 23:07:49

Band2_3MHz_QPSK_18900_1RB#0_30~1000_3
0~1000



Date: 2.JUL.2024 23:08:03


Band2_3MHz_QPSK_18900_1RB#0_1000~3000_1
1000~3000



Date: 2.JUL.2024 23:08:18

Date: 2.JUL.2024 23:08:27


Band2_3MHz_QPSK_18900_1RB#0_3000~2000 0_3000~20000	Band2_3MHz_16QAM_18900_1RB#0_0.009~0.15 _0.009~0.15
---	--



Date: 2.JUL.2024 23:08:42


Date: 2.JUL.2024 23:08:56

Band2_3MHz_16QAM_18900_1RB#0_0.15~30 0.15~30	Band2_3MHz_16QAM_18900_1RB#0_30~1000_3 0~1000
---	--




Date: 2.JUL.2024 23:09:10

Band2_3MHz_16QAM_18900_1RB#0_1000~3000_0_1000~3000




Date: 2.JUL.2024 23:09:25

Band2_3MHz_16QAM_18900_1RB#0_3000~20000_0_3000~20000




Date: 2.JUL.2024 23:09:35

Band2_3MHz_QPSK_18900_1RB#14_0.009~0.15_0.009~0.15



Date: 2.JUL.2024 23:09:50


Band2_3MHz_QPSK_18900_1RB#14_0.15~30_0.15~30



Date: 2.JUL.2024 23:10:04

Date: 2.JUL.2024 23:10:17


Band2_3MHz_QPSK_18900_1RB#14_30~1000_30~1000	Band2_3MHz_QPSK_18900_1RB#14_1000~3000_1000~3000
--	--



Date: 2.JUL.2024 23:10:32

Date: 2.JUL.2024 23:10:42

Band2_3MHz_QPSK_18900_1RB#14_3000~20000_3000~20000	Band2_3MHz_16QAM_18900_1RB#14_0.009~0.15_0.009~0.15
--	---




Date: 2.JUL.2024 23:10:57

Date: 2.JUL.2024 23:11:10

Band2_3MHz_16QAM_18900_1RB#14_0.15~30_0.15~30

Band2_3MHz_16QAM_18900_1RB#14_30~1000_30~1000




Date: 2.JUL.2024 23:11:24

Date: 2.JUL.2024 23:11:39


Band2_3MHz_16QAM_18900_1RB#14_1000~3000_00_1000~3000

Band2_3MHz_16QAM_18900_1RB#14_3000~20000_00_3000~20000




Date: 2.JUL.2024 23:11:50

Band2_3MHz_QPSK_18900_15RB#0_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:12:05

Band2_3MHz_QPSK_18900_15RB#0_0.15~30_0.
15~30




Date: 2.JUL.2024 23:12:18

Band2_3MHz_QPSK_18900_15RB#0_30~1000_
30~1000



Date: 2.JUL.2024 23:12:32


Band2_3MHz_QPSK_18900_15RB#0_1000~3000
_1000~3000



Date: 2.JUL.2024 23:12:47

Date: 2.JUL.2024 23:12:56


Band2_3MHz_QPSK_18900_15RB#0_3000~20000_3000~20000	Band2_3MHz_16QAM_18900_15RB#0_0.009~0.15_5_0.009~0.15
--	---



Date: 2.JUL.2024 23:13:11


Date: 2.JUL.2024 23:13:25

Band2_3MHz_16QAM_18900_15RB#0_0.15~30_0.15~30	Band2_3MHz_16QAM_18900_15RB#0_30~1000_30~1000
---	---




Date: 2.JUL.2024 23:13:39

Band2_3MHz_16QAM_18900_15RB#0_1000~3000_00_1000~3000




Date: 2.JUL.2024 23:13:54

Band2_3MHz_16QAM_18900_15RB#0_3000~20000_00_3000~20000




Date: 2.JUL.2024 23:14:06

Band2_3MHz_QPSK_19185_1RB#0_0.009~0.15_0.009~0.15



Date: 2.JUL.2024 23:14:21


Band2_3MHz_QPSK_19185_1RB#0_0.15~30_0.15~30



Date: 2.JUL.2024 23:14:35

Date: 2.JUL.2024 23:14:48


Band2_3MHz_QPSK_19185_1RB#0_30~1000_3 0~1000	Band2_3MHz_QPSK_19185_1RB#0_1000~3000_ 1000~3000
---	---



Date: 2.JUL.2024 23:15:03

Date: 2.JUL.2024 23:15:13


Band2_3MHz_QPSK_19185_1RB#0_3000~2000 0_3000~20000	Band2_3MHz_16QAM_19185_1RB#0_0.009~0.15 _0.009~0.15
---	--



Date: 2.JUL.2024 23:15:28

Date: 2.JUL.2024 23:15:41


Band2_3MHz_16QAM_19185_1RB#0_0.15~30_0.15~30	Band2_3MHz_16QAM_19185_1RB#0_30~1000_30~1000
--	--



Date: 2.JUL.2024 23:15:55


Date: 2.JUL.2024 23:16:10

Band2_3MHz_16QAM_19185_1RB#0_1000~3000_1000~3000	Band2_3MHz_16QAM_19185_1RB#0_3000~20000_3000~20000
--	--




Date: 2.JUL.2024 23:16:21

Band2_3MHz_QPSK_19185_1RB#14_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:16:36

Band2_3MHz_QPSK_19185_1RB#14_0.15~30_0.
15~30




Date: 2.JUL.2024 23:16:50

Band2_3MHz_QPSK_19185_1RB#14_30~1000_
30~1000



Date: 2.JUL.2024 23:17:03


Band2_3MHz_QPSK_19185_1RB#14_1000~3000
_1000~3000



Date: 2.JUL.2024 23:17:18

Date: 2.JUL.2024 23:17:28


Band2_3MHz_QPSK_19185_1RB#14_3000~20000_3000~20000	Band2_3MHz_16QAM_19185_1RB#14_0.009~0.15_0.009~0.15
--	---



Date: 2.JUL.2024 23:17:43

Date: 2.JUL.2024 23:17:56


Band2_3MHz_16QAM_19185_1RB#14_0.15~30_0.15~30	Band2_3MHz_16QAM_19185_1RB#14_30~1000_30~1000
---	---



Date: 2.JUL.2024 23:18:10

Date: 2.JUL.2024 23:18:25


Band2_3MHz_16QAM_19185_1RB#14_1000~3000_1000~3000	Band2_3MHz_16QAM_19185_1RB#14_3000~2000_3000~20000
---	--



Date: 2.JUL.2024 23:18:36

Date: 2.JUL.2024 23:18:51


Band2_3MHz_QPSK_19185_15RB#0_0.009~0.15_0.009~0.15	Band2_3MHz_QPSK_19185_15RB#0_0.15~30_0.15~30
--	--



Date: 2.JUL.2024 23:19:05

Date: 2.JUL.2024 23:19:18


Band2_3MHz_QPSK_19185_15RB#0_30~1000_30~1000	Band2_3MHz_QPSK_19185_15RB#0_1000~3000_1000~3000
--	--



Date: 2.JUL.2024 23:19:33

Date: 2.JUL.2024 23:19:43

Band2_3MHz_QPSK_19185_15RB#0_3000~20000_3000~20000	Band2_3MHz_16QAM_19185_15RB#0_0.009~0.15_0.009~0.15
--	---




Date: 2.JUL.2024 23:19:58

Date: 2.JUL.2024 23:20:12

Band2_3MHz_16QAM_19185_15RB#0_0.15~30
_0.15~30

Band2_3MHz_16QAM_19185_15RB#0_30~1000_
30~1000




Date: 2.JUL.2024 23:20:25

Date: 2.JUL.2024 23:20:40


Band2_3MHz_16QAM_19185_15RB#0_1000~30
00_1000~3000

Band2_3MHz_16QAM_19185_15RB#0_3000~200
00_3000~20000




Date: 2.JUL.2024 23:53:21

Band2_5MHz_QPSK_18625_1RB#0_0.009~0.15
_0.009~0.15




Date: 2.JUL.2024 23:53:36

Band2_5MHz_QPSK_18625_1RB#0_0.15~30_0.1
5~30




Date: 2.JUL.2024 23:53:50

Band2_5MHz_QPSK_18625_1RB#0_30~1000_3
0~1000



Date: 2.JUL.2024 23:54:03


Band2_5MHz_QPSK_18625_1RB#0_1000~3000_
1000~3000



Date: 2.JUL.2024 23:54:18

Date: 2.JUL.2024 23:54:26


Band2_5MHz_QPSK_18625_1RB#0_3000~2000 0_3000~20000	Band2_5MHz_16QAM_18625_1RB#0_0.009~0.15 _0.009~0.15
---	--



Date: 2.JUL.2024 23:54:41


Date: 2.JUL.2024 23:54:55

Band2_5MHz_16QAM_18625_1RB#0_0.15~30 0.15~30	Band2_5MHz_16QAM_18625_1RB#0_30~1000_3 0~1000
---	--




Date: 2.JUL.2024 23:55:09

Band2_5MHz_16QAM_18625_1RB#0_1000~3000
0_1000~3000




Date: 2.JUL.2024 23:55:24

Band2_5MHz_16QAM_18625_1RB#0_3000~20000
0_3000~20000




Date: 2.JUL.2024 23:55:35

Band2_5MHz_QPSK_18625_1RB#24_0.009~0.1
5_0.009~0.15




Date: 2.JUL.2024 23:55:50

Band2_5MHz_QPSK_18625_1RB#24_0.15~30_0.
15~30




Date: 2.JUL.2024 23:56:03

Band2_5MHz_QPSK_18625_1RB#24_30~1000_30~1000




Date: 2.JUL.2024 23:56:17

Band2_5MHz_QPSK_18625_1RB#24_1000~3000_1000~3000




Date: 2.JUL.2024 23:56:31

Band2_5MHz_QPSK_18625_1RB#24_3000~20000_3000~20000



Date: 2.JUL.2024 23:56:40


Band2_5MHz_16QAM_18625_1RB#24_0.009~0.15_0.009~0.15



Date: 2.JUL.2024 23:56:54

Date: 2.JUL.2024 23:57:08


Band2_5MHz_16QAM_18625_1RB#24_0.15~30_0.15~30	Band2_5MHz_16QAM_18625_1RB#24_30~1000_30~1000
---	---



Date: 2.JUL.2024 23:57:21


Date: 2.JUL.2024 23:57:36

Band2_5MHz_16QAM_18625_1RB#24_1000~3000_00_1000~3000	Band2_5MHz_16QAM_18625_1RB#24_3000~20000_00_3000~20000
--	--




Date: 2.JUL.2024 23:57:47

Band2_5MHz_QPSK_18625_25RB#0_0.009~0.15
5_0.009~0.15




Date: 2.JUL.2024 23:58:02

Band2_5MHz_QPSK_18625_25RB#0_0.15~30_0.
15~30




Date: 2.JUL.2024 23:58:15

Band2_5MHz_QPSK_18625_25RB#0_30~1000_
30~1000



Date: 2.JUL.2024 23:58:29


Band2_5MHz_QPSK_18625_25RB#0_1000~3000
_1000~3000



Date: 2.JUL.2024 23:58:43

Date: 2.JUL.2024 23:58:52


Band2_5MHz_QPSK_18625_25RB#0_3000~20000_00_3000~20000	Band2_5MHz_16QAM_18625_25RB#0_0.009~0.15_5_0.009~0.15
---	---



Date: 2.JUL.2024 23:59:06


Date: 2.JUL.2024 23:59:20

Band2_5MHz_16QAM_18625_25RB#0_0.15~30_0.15~30	Band2_5MHz_16QAM_18625_25RB#0_30~1000_30~1000
---	---




Date: 2.JUL.2024 23:59:33

Band2_5MHz_16QAM_18625_25RB#0_1000~3000
00_1000~3000




Date: 2.JUL.2024 23:59:48

Band2_5MHz_16QAM_18625_25RB#0_3000~20000
00_3000~20000




Date: 3.JUL.2024 00:00:00

Band2_5MHz_QPSK_18900_1RB#0_0.009~0.15
_0.009~0.15




Date: 3.JUL.2024 00:00:15

Band2_5MHz_QPSK_18900_1RB#0_0.15~30_0.1
5~30




Date: 3.JUL.2024 00:00:28

Band2_5MHz_QPSK_18900_1RB#0_30~1000_3
0~1000




Date: 3.JUL.2024 00:00:42

Band2_5MHz_QPSK_18900_1RB#0_1000~3000_
1000~3000




Date: 3.JUL.2024 00:00:57

Band2_5MHz_QPSK_18900_1RB#0_3000~2000_
0_3000~20000



Date: 3.JUL.2024 00:01:05


Band2_5MHz_16QAM_18900_1RB#0_0.009~0.15_
_0.009~0.15



Date: 3.JUL.2024 00:01:20

Date: 3.JUL.2024 00:01:33


Band2_5MHz_16QAM_18900_1RB#0_0.15~30_0.15~30	Band2_5MHz_16QAM_18900_1RB#0_30~1000_30~1000
--	--



Date: 3.JUL.2024 00:01:47


Date: 3.JUL.2024 00:02:02

Band2_5MHz_16QAM_18900_1RB#0_1000~3000_1000~3000	Band2_5MHz_16QAM_18900_1RB#0_3000~20000_3000~20000
--	--




Date: 3.JUL.2024 00:02:13

Band2_5MHz_QPSK_18900_1RB#24_0.009~0.15_5_0.009~0.15




Date: 3.JUL.2024 00:02:28

Band2_5MHz_QPSK_18900_1RB#24_0.15~30_0.15~30




Date: 3.JUL.2024 00:02:41

Band2_5MHz_QPSK_18900_1RB#24_30~1000_30~1000



Date: 3.JUL.2024 00:02:55


Band2_5MHz_QPSK_18900_1RB#24_1000~3000_1000~3000



Date: 3.JUL.2024 00:03:10

Date: 3.JUL.2024 00:03:18


Band2_5MHz_QPSK_18900_1RB#24_3000~20000_3000~20000	Band2_5MHz_16QAM_18900_1RB#24_0.009~0.15_0.009~0.15
--	---



Date: 3.JUL.2024 00:03:33


Date: 3.JUL.2024 00:03:47

Band2_5MHz_16QAM_18900_1RB#24_0.15~30_0.15~30	Band2_5MHz_16QAM_18900_1RB#24_30~1000_30~1000
---	---




Date: 3.JUL.2024 00:04:01

Band2_5MHz_16QAM_18900_1RB#24_1000~3000_1000~3000




Date: 3.JUL.2024 00:04:16

Band2_5MHz_16QAM_18900_1RB#24_3000~20000_3000~20000




Date: 3.JUL.2024 00:04:26

Band2_5MHz_QPSK_18900_25RB#0_0.009~0.15_0.009~0.15



Date: 3.JUL.2024 00:04:41


Band2_5MHz_QPSK_18900_25RB#0_0.15~30_0.15~30



Date: 3.JUL.2024 00:04:55

Date: 3.JUL.2024 00:05:09


Band2_5MHz_QPSK_18900_25RB#0_30~1000_30~1000	Band2_5MHz_QPSK_18900_25RB#0_1000~3000_1000~3000
--	--



Date: 3.JUL.2024 00:05:24

Date: 3.JUL.2024 00:05:32

Band2_5MHz_QPSK_18900_25RB#0_3000~20000_3000~20000	Band2_5MHz_16QAM_18900_25RB#0_0.009~0.15_0.009~0.15
--	---




Date: 3.JUL.2024 00:05:47

Date: 3.JUL.2024 00:06:00

Band2_5MHz_16QAM_18900_25RB#0_0.15~30_0.15~30

Band2_5MHz_16QAM_18900_25RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:06:14

Date: 3.JUL.2024 00:06:29


Band2_5MHz_16QAM_18900_25RB#0_1000~3000_00_1000~3000

Band2_5MHz_16QAM_18900_25RB#0_3000~20000_00_3000~20000




Date: 3.JUL.2024 00:06:42

Band2_5MHz_QPSK_19175_1RB#0_0.009~0.15
_0.009~0.15




Date: 3.JUL.2024 00:06:57

Band2_5MHz_QPSK_19175_1RB#0_0.15~30_0.1
5~30




Date: 3.JUL.2024 00:07:11

Band2_5MHz_QPSK_19175_1RB#0_30~1000_3
0~1000



Date: 3.JUL.2024 00:07:24

Band2_5MHz_QPSK_19175_1RB#0_1000~3000_1
1000~3000




Date: 3.JUL.2024 00:07:40

Date: 3.JUL.2024 00:07:48

Band2_5MHz_QPSK_19175_1RB#0_3000~2000
0_3000~20000

Band2_5MHz_16QAM_19175_1RB#0_0.009~0.15
_0.009~0.15




Date: 3.JUL.2024 00:08:03

Date: 3.JUL.2024 00:08:17

Band2_5MHz_16QAM_19175_1RB#0_0.15~30
0.15~30


Band2_5MHz_16QAM_19175_1RB#0_30~1000_3
0~1000



Date: 3.JUL.2024 00:08:30

Date: 3.JUL.2024 00:08:45


Band2_5MHz_16QAM_19175_1RB#0_1000~3000 0_1000~3000	Band2_5MHz_16QAM_19175_1RB#0_3000~2000 0_3000~20000
---	--



Date: 3.JUL.2024 00:08:56


Date: 3.JUL.2024 00:09:11

Band2_5MHz_QPSK_19175_1RB#24_0.009~0.1 5_0.009~0.15	Band2_5MHz_QPSK_19175_1RB#24_0.15~30_0. 15~30
--	--




Date: 3.JUL.2024 00:09:25

Band2_5MHz_QPSK_19175_1RB#24_30~1000_30~1000




Date: 3.JUL.2024 00:09:38

Band2_5MHz_QPSK_19175_1RB#24_1000~3000_1000~3000




Date: 3.JUL.2024 00:09:53

Band2_5MHz_QPSK_19175_1RB#24_3000~20000_3000~20000



Date: 3.JUL.2024 00:10:02

Band2_5MHz_16QAM_19175_1RB#24_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:10:17

Date: 3.JUL.2024 00:10:30

Band2_5MHz_16QAM_19175_1RB#24_0.15~30_0.15~30

Band2_5MHz_16QAM_19175_1RB#24_30~1000_30~1000




Date: 3.JUL.2024 00:10:44

Date: 3.JUL.2024 00:10:59


Band2_5MHz_16QAM_19175_1RB#24_1000~3000_00_1000~3000

Band2_5MHz_16QAM_19175_1RB#24_3000~20000_00_3000~20000




Date: 3.JUL.2024 00:11:09

Band2_5MHz_QPSK_19175_25RB#0_0.009~0.15
5_0.009~0.15




Date: 3.JUL.2024 00:11:25

Band2_5MHz_QPSK_19175_25RB#0_0.15~30_0.
15~30




Date: 3.JUL.2024 00:11:38

Band2_5MHz_QPSK_19175_25RB#0_30~1000_
30~1000



Date: 3.JUL.2024 00:11:52


Band2_5MHz_QPSK_19175_25RB#0_1000~3000_
_1000~3000



Date: 3.JUL.2024 00:12:07

Date: 3.JUL.2024 00:12:15


Band2_5MHz_QPSK_19175_25RB#0_3000~20000_3000~20000	Band2_5MHz_16QAM_19175_25RB#0_0.009~0.15_5_0.009~0.15
--	---



Date: 3.JUL.2024 00:12:30


Date: 3.JUL.2024 00:12:43

Band2_5MHz_16QAM_19175_25RB#0_0.15~30_0.15~30	Band2_5MHz_16QAM_19175_25RB#0_30~1000_30~1000
---	---




Date: 3.JUL.2024 00:12:57

Band2_5MHz_16QAM_19175_25RB#0_1000~3000_00_1000~3000




Date: 3.JUL.2024 00:13:12

Band2_5MHz_16QAM_19175_25RB#0_3000~20000_00_3000~20000




Date: 3.JUL.2024 00:44:39

Band2_10MHz_QPSK_18650_1RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:44:54

Band2_10MHz_QPSK_18650_1RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:45:07

Band2_10MHz_QPSK_18650_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:45:21

Band2_10MHz_QPSK_18650_1RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:45:36

Band2_10MHz_QPSK_18650_1RB#0_3000~20000_3000~20000




Date: 3.JUL.2024 00:45:44

Band2_10MHz_16QAM_18650_1RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:45:59

Band2_10MHz_16QAM_18650_1RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:46:12

Band2_10MHz_16QAM_18650_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:46:25

Band2_10MHz_16QAM_18650_1RB#0_1000~30_00_1000~3000




Date: 3.JUL.2024 00:46:40

Band2_10MHz_16QAM_18650_1RB#0_3000~200_00_3000~20000




Date: 3.JUL.2024 00:46:51




Date: 3.JUL.2024 00:47:06

Band2_10MHz_QPSK_18650_1RB#49_0.009~0.15_0.009~0.15

Band2_10MHz_QPSK_18650_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 00:47:19



Date: 3.JUL.2024 00:47:33

Band2_10MHz_QPSK_18650_1RB#49_30~1000_30~1000

Band2_10MHz_QPSK_18650_1RB#49_1000~3000_0_1000~3000




Date: 3.JUL.2024 00:47:47

Date: 3.JUL.2024 00:47:55

Band2_10MHz_QPSK_18650_1RB#49_3000~20000_3000~20000

Band2_10MHz_16QAM_18650_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:48:10

Date: 3.JUL.2024 00:48:24


Band2_10MHz_16QAM_18650_1RB#49_0.15~30_0.15~30

Band2_10MHz_16QAM_18650_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 00:48:37

Band2_10MHz_16QAM_18650_1RB#49_1000~3000_1000~3000




Date: 3.JUL.2024 00:48:52

Band2_10MHz_16QAM_18650_1RB#49_3000~20000_000_3000~20000




Date: 3.JUL.2024 00:49:03

Band2_10MHz_QPSK_18650_50RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:49:18

Band2_10MHz_QPSK_18650_50RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:49:31

Band2_10MHz_QPSK_18650_50RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:49:44

Band2_10MHz_QPSK_18650_50RB#0_1000~3000_0_1000~3000




Date: 3.JUL.2024 00:49:59

Band2_10MHz_QPSK_18650_50RB#0_3000~20000_000_3000~20000



Date: 3.JUL.2024 00:50:07


Band2_10MHz_16QAM_18650_50RB#0_0.009~0.15_0.009~0.15



Date: 3.JUL.2024 00:50:22

Date: 3.JUL.2024 00:50:36


Band2_10MHz_16QAM_18650_50RB#0_0.15~3 0_0.15~30	Band2_10MHz_16QAM_18650_50RB#0_30~1000 _30~1000
--	--



Date: 3.JUL.2024 00:50:49


Date: 3.JUL.2024 00:51:04

Band2_10MHz_16QAM_18650_50RB#0_1000~3 000_1000~3000	Band2_10MHz_16QAM_18650_50RB#0_3000~20 000_3000~20000
--	--




Date: 3.JUL.2024 00:51:16

Band2_10MHz_QPSK_18900_1RB#0_0.009~0.15
5_0.009~0.15




Date: 3.JUL.2024 00:51:31

Band2_10MHz_QPSK_18900_1RB#0_0.15~30_0.
15~30




Date: 3.JUL.2024 00:51:44

Band2_10MHz_QPSK_18900_1RB#0_30~1000_
30~1000



Date: 3.JUL.2024 00:51:58


Band2_10MHz_QPSK_18900_1RB#0_1000~3000
_1000~3000



Date: 3.JUL.2024 00:52:12

Date: 3.JUL.2024 00:52:20


Band2_10MHz_QPSK_18900_1RB#0_3000~20000_3000~20000	Band2_10MHz_16QAM_18900_1RB#0_0.009~0.15_5_0.009~0.15
--	---



Date: 3.JUL.2024 00:52:35


Date: 3.JUL.2024 00:52:49

Band2_10MHz_16QAM_18900_1RB#0_0.15~30_0.15~30	Band2_10MHz_16QAM_18900_1RB#0_30~1000_30~1000
---	---




Date: 3.JUL.2024 00:53:02

Band2_10MHz_16QAM_18900_1RB#0_1000~3000_00_1000~3000




Date: 3.JUL.2024 00:53:17

Band2_10MHz_16QAM_18900_1RB#0_3000~20000_00_3000~20000




Date: 3.JUL.2024 00:53:28

Band2_10MHz_QPSK_18900_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:53:42

Band2_10MHz_QPSK_18900_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 00:53:56

Band2_10MHz_QPSK_18900_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 00:54:09

Band2_10MHz_QPSK_18900_1RB#49_1000~3000_0_1000~3000




Date: 3.JUL.2024 00:54:24

Band2_10MHz_QPSK_18900_1RB#49_3000~20000_000_3000~20000



Date: 3.JUL.2024 00:54:32


Band2_10MHz_16QAM_18900_1RB#49_0.009~0.15_0.009~0.15



Date: 3.JUL.2024 00:54:47

Date: 3.JUL.2024 00:55:00


Band2_10MHz_16QAM_18900_1RB#49_0.15~3 0_0.15~30	Band2_10MHz_16QAM_18900_1RB#49_30~1000 _30~1000
--	--



Date: 3.JUL.2024 00:55:14


Date: 3.JUL.2024 00:55:28

Band2_10MHz_16QAM_18900_1RB#49_1000~3 000_1000~3000	Band2_10MHz_16QAM_18900_1RB#49_3000~20 000_3000~20000
--	--




Date: 3.JUL.2024 00:55:39

Band2_10MHz_QPSK_18900_50RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:55:54

Band2_10MHz_QPSK_18900_50RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:56:08

Band2_10MHz_QPSK_18900_50RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:56:21


Band2_10MHz_QPSK_18900_50RB#0_1000~3000_0_1000~3000




Band2_10MHz_QPSK_18900_50RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_18900_50RB#0_0.009~0.15_0.009~0.15



Band2_10MHz_16QAM_18900_50RB#0_0.15~3
0_0.15~30




Band2_10MHz_16QAM_18900_50RB#0_30~1000
_30~1000




Date: 3.JUL.2024 00:57:28

Band2_10MHz_16QAM_18900_50RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:57:43

Band2_10MHz_16QAM_18900_50RB#0_3000~20000_000_3000~20000




Date: 3.JUL.2024 00:57:55

Band2_10MHz_QPSK_19150_1RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:58:10

Band2_10MHz_QPSK_19150_1RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:58:24

Band2_10MHz_QPSK_19150_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:58:37

Band2_10MHz_QPSK_19150_1RB#0_1000~3000_1000~3000




Date: 3.JUL.2024 00:58:52

Band2_10MHz_QPSK_19150_1RB#0_3000~20000_3000~20000




Date: 3.JUL.2024 00:59:00

Band2_10MHz_16QAM_19150_1RB#0_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 00:59:15

Band2_10MHz_16QAM_19150_1RB#0_0.15~30_0.15~30




Date: 3.JUL.2024 00:59:28

Band2_10MHz_16QAM_19150_1RB#0_30~1000_30~1000




Date: 3.JUL.2024 00:59:41

Band2_10MHz_16QAM_19150_1RB#0_1000~30_00_1000~3000




Date: 3.JUL.2024 00:59:56

Band2_10MHz_16QAM_19150_1RB#0_3000~200_00_3000~20000




Date: 3.JUL.2024 01:00:07

Band2_10MHz_QPSK_19150_1RB#49_0.009~0.15_0.009~0.15




Date: 3.JUL.2024 01:00:22

Band2_10MHz_QPSK_19150_1RB#49_0.15~30_0.15~30




Date: 3.JUL.2024 01:00:35

Band2_10MHz_QPSK_19150_1RB#49_30~1000_30~1000




Date: 3.JUL.2024 01:00:49

Band2_10MHz_QPSK_19150_1RB#49_1000~3000_0_1000~3000




Date: 3.JUL.2024 01:01:03

Band2_10MHz_QPSK_19150_1RB#49_3000~20000_3000~20000




Date: 3.JUL.2024 01:01:11

Band2_10MHz_16QAM_19150_1RB#49_0.009~0.15_0.009~0.15



Date: 3.JUL.2024 01:01:26

Band2_10MHz_16QAM_19150_1RB#49_0.15~30_0.15~30



Date: 3.JUL.2024 01:01:40

Band2_10MHz_16QAM_19150_1RB#49_30~1000_30~1000