

FCC ID: 2AXIALTRA072


Transmitter power attestation

We hereby declare that the equipment test sample provided for testing was configured to operate with maximum transmitter power.

The differences in transmitter power values between Tune-Up Information and named tests are caused by different measurement equipment resolution bandwidths and duty cycle related measurements.

The measured transmitter power values of test report regarding FCC Parts 15.209(a) & 15.247 are related to duty cycle and the equipment resolution bandwidths employed in accordance with ANSI 63.10 procedures.

Signature: _____


Michael Thomasius
Chief Technology Officer (CTO)

Date: 09/11/2021