

FCC ID: 2AXIALTRA073


Transmitter power attestation

We hereby declare that the equipment test sample provided for testing was configured to operate with maximum transmitter power.

The differences in transmitter power values between Tune-Up Information and named tests are caused by different measurement equipment resolution bandwidths and duty cycle related measurements.

The measured transmitter power values of test report regarding FCC Parts 15.209(a) & 15.247 are related to duty cycle and the equipment resolution bandwidths employed in accordance with ANSI 63.10 procedures.

Signature: _____


Michael Thomasius
Chief Technology Officer (CTO)

Date: 09/11/2021


09/11/2021 | Page 1

ST Sportservice GmbH
Wiesenring 11
D-04159 Leipzig - Germany

Phone +49 341 46 21 100
office@st-sportservice.com
www.swisstiming.com

Managing Director: A. Zobrist
District Court: Leipzig HRB 2325
TAX ID: DE 141 499 042

Chairman of the Supervisory Board: Georges N. Hayek
Deutsche Bank AG Köln - Swift DEUTDE33
IBAN DE58370700600120480900

A COMPANY OF THE  **SWATCH GROUP** OF SWITZERLAND