




11BE80MIMO_Ant3_6865




11BE80MIMO_Ant4_6865




11BE80MIMO_Ant9_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant10_6865




11BE80MIMO_Ant3_6945




11BE80MIMO_Ant4_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant9_6945




11BE80MIMO_Ant10_6945




11BE80MIMO_Ant3_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_7025



11BE80MIMO_Ant9_7025




11BE80MIMO_Ant10_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant3_6185



11BE160MIMO_Ant4_6185



11BE160MIMO_Ant9_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant10_6185



11BE160MIMO_Ant3_6345




11BE160MIMO_Ant4_6345

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant9_6345



11BE160MIMO_Ant10_6345




11BE160MIMO_Ant3_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant4_6505



11BE160MIMO_Ant9_6505




11BE160MIMO_Ant10_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant3_6665



11BE160MIMO_Ant4_6665



11BE160MIMO_Ant9_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant10_6665




11BE160MIMO_Ant3_6825




11BE160MIMO_Ant4_6825


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant9_6825



11BE160MIMO_Ant10_6825




11BE160MIMO_Ant3_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant4_6985




11BE160MIMO_Ant9_6985




11BE160MIMO_Ant10_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant3_6265



11BE320MIMO_Ant4_6265




11BE320MIMO_Ant9_6265


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant10_6265




11BE320MIMO_Ant3_6425




11BE320MIMO_Ant4_6425


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant9_6425



11BE320MIMO_Ant10_6425




11BE320MIMO_Ant3_6585


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant4_6585




11BE320MIMO_Ant9_6585




11BE320MIMO_Ant10_6585


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant3_6745




11BE320MIMO_Ant4_6745




11BE320MIMO_Ant9_6745


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE320MIMO_Ant10_6745



11BE320MIMO_Ant3_6905



11BE320MIMO_Ant4_6905

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.