




11G-CDD_Ant3_2457_0~Reference




11G-CDD_Ant3_2457_30~1000




11G-CDD_Ant3_2457_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant1_2462_0~Reference




11G-CDD_Ant1_2462_30~1000




11G-CDD_Ant1_2462_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant3_2462_0~Reference




11G-CDD_Ant3_2462_30~1000




11G-CDD_Ant3_2462_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2412_0~Reference




11AX20-CDD_Ant1_2412_30~1000




11AX20-CDD_Ant1_2412_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2412_0~Reference




11AX20-CDD_Ant3_2412_30~1000




11AX20-CDD_Ant3_2412_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2417_0~Reference




11AX20-CDD_Ant1_2417_30~1000




11AX20-CDD_Ant1_2417_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2417_0~Reference




11AX20-CDD_Ant3_2417_30~1000




11AX20-CDD_Ant3_2417_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2437_0~Reference




11AX20-CDD_Ant1_2437_30~1000




11AX20-CDD_Ant1_2437_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2437_0~Reference




11AX20-CDD_Ant3_2437_30~1000




11AX20-CDD_Ant3_2437_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2457_0~Reference




11AX20-CDD_Ant1_2457_30~1000




11AX20-CDD_Ant1_2457_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2457_0~Reference




11AX20-CDD_Ant3_2457_30~1000




11AX20-CDD_Ant3_2457_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2462_0~Reference




11AX20-CDD_Ant1_2462_30~1000




11AX20-CDD_Ant1_2462_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2462_0~Reference



11AX20-CDD_Ant3_2462_30~1000




11AX20-CDD_Ant3_2462_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2422_0~Reference




11AX40-CDD_Ant1_2422_30~1000




11AX40-CDD_Ant1_2422_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2422_0~Reference



11AX40-CDD_Ant3_2422_30~1000




11AX40-CDD_Ant3_2422_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2427_0~Reference




11AX40-CDD_Ant1_2427_30~1000




11AX40-CDD_Ant1_2427_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2427_0~Reference




11AX40-CDD_Ant3_2427_30~1000




11AX40-CDD_Ant3_2427_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2437_0~Reference




11AX40-CDD_Ant1_2437_30~1000




11AX40-CDD_Ant1_2437_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2437_0~Reference




11AX40-CDD_Ant3_2437_30~1000




11AX40-CDD_Ant3_2437_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2447_0~Reference




11AX40-CDD_Ant1_2447_30~1000




11AX40-CDD_Ant1_2447_1000~26500


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2447_0~Reference



11AX40-CDD_Ant3_2447_30~1000



11AX40-CDD_Ant3_2447_1000~26500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.