

11B-CDD_Ant1_2457



11B-CDD_Ant3_2457



11B-CDD_Ant1_2462

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant3_2462



11G-CDD_Ant1_2412



11G-CDD_Ant3_2412

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant1_2417



11G-CDD_Ant3_2417



11G-CDD_Ant1_2437

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant3_2437



11G-CDD_Ant1_2457



11G-CDD_Ant3_2457

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant1_2462



11G-CDD_Ant3_2462



11AX20-CDD_Ant1_2412

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2412



11AX20-CDD_Ant1_2417



11AX20-CDD_Ant3_2417

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_2437



11AX20-CDD_Ant3_2437



11AX20-CDD_Ant1_2457

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_2457



11AX20-CDD_Ant1_2462



11AX20-CDD_Ant3_2462

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2422



11AX40-CDD_Ant3_2422



11AX40-CDD_Ant1_2427

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2427



11AX40-CDD_Ant1_2437



11AX40-CDD_Ant3_2437

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_2447



11AX40-CDD_Ant3_2447



11AX40-CDD_Ant1_2452

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_2452

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11.5. APPENDIX E: BAND EDGE MEASUREMENTS

11.5.1. Test Result

Test Mode	Antenna	ChName	Channel	RefLevel[dBm]	Result[dBm]	Limit[dBm]	Verdict
11B-CDD	Ant1	Low	2412	14.54	-34.19	≤-15.46	PASS
	Ant3	Low	2412	13.05	-36.17	≤-16.95	PASS
	Ant1	Low	2417	14.99	-37.03	≤-15.01	PASS
	Ant3	Low	2417	13.73	-36.77	≤-16.27	PASS
	Ant1	High	2457	13.73	-37.82	≤-16.27	PASS
	Ant3	High	2457	14.61	-37.52	≤-15.39	PASS
	Ant1	High	2462	14.58	-37.35	≤-15.42	PASS
	Ant3	High	2462	15.26	-36.83	≤-14.74	PASS
11G-CDD	Ant1	Low	2412	12.40	-25.36	≤-17.6	PASS
	Ant3	Low	2412	10.74	-25.82	≤-19.26	PASS
	Ant1	Low	2417	12.58	-34.37	≤-17.43	PASS
	Ant3	Low	2417	10.90	-36.11	≤-19.1	PASS
	Ant1	High	2457	11.47	-36.26	≤-18.53	PASS
	Ant3	High	2457	12.48	-37.47	≤-17.53	PASS
	Ant1	High	2462	11.62	-36.54	≤-18.38	PASS
	Ant3	High	2462	12.27	-36.59	≤-17.73	PASS
11AX20-CDD	Ant1	Low	2412	12.86	-18.84	≤-17.14	PASS
	Ant3	Low	2412	12.33	-20.52	≤-17.67	PASS
	Ant1	Low	2417	12.77	-33.16	≤-17.23	PASS
	Ant3	Low	2417	12.35	-31.45	≤-17.65	PASS
	Ant1	High	2457	13.39	-37.6	≤-16.61	PASS
	Ant3	High	2457	12.68	-37.16	≤-17.32	PASS
	Ant1	High	2462	12.97	-34.56	≤-17.04	PASS
	Ant3	High	2462	12.91	-36.34	≤-17.09	PASS
11AX40-CDD	Ant1	Low	2422	9.38	-25.98	≤-20.62	PASS
	Ant3	Low	2422	9.36	-24.66	≤-20.64	PASS
	Ant1	Low	2427	9.48	-30.28	≤-20.52	PASS
	Ant3	Low	2427	9.58	-29.78	≤-20.43	PASS
	Ant1	High	2447	9.38	-34.09	≤-20.62	PASS
	Ant3	High	2447	9.43	-32.12	≤-20.58	PASS
	Ant1	High	2452	10.06	-29.77	≤-19.94	PASS
	Ant3	High	2452	8.56	-30.91	≤-21.44	PASS

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11.5.2. Test Graphs



11B-CDD_Ant1_Low_2412



11B-CDD_Ant3_Low_2412



11B-CDD_Ant1_Low_2417

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant3_Low_2417



11B-CDD_Ant1_High_2457



11B-CDD_Ant3_High_2457

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant1_High_2462



11B-CDD_Ant3_High_2462



11G-CDD_Ant1_Low_2412

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant3_Low_2412



11G-CDD_Ant1_Low_2417



11G-CDD_Ant3_Low_2417

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant1_High_2457



11G-CDD_Ant3_High_2457



11G-CDD_Ant1_High_2462

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant3_High_2462



11AX20-CDD_Ant1_Low_2412



11AX20-CDD_Ant3_Low_2412

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_Low_2417



11AX20-CDD_Ant3_Low_2417



11AX20-CDD_Ant1_High_2457

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_High_2457



11AX20-CDD_Ant1_High_2462



11AX20-CDD_Ant3_High_2462

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.