

11BE20MIMO_Ant3_6435



11BE20MIMO_Ant4_6435



11BE20MIMO_Ant5_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6435



11BE20MIMO_Ant3_6475



11BE20MIMO_Ant4_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6475



11BE20MIMO_Ant6_6475



11BE20MIMO_Ant3_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6515



11BE20MIMO_Ant5_6515



11BE20MIMO_Ant6_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6535



11BE20MIMO_Ant4_6535



11BE20MIMO_Ant5_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6535



11BE20MIMO_Ant3_6715



11BE20MIMO_Ant4_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6715



11BE20MIMO_Ant6_6715



11BE20MIMO_Ant3_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6875



11BE20MIMO_Ant5_6875



11BE20MIMO_Ant6_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6895



11BE20MIMO_Ant4_6895



11BE20MIMO_Ant5_6895

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6895



11BE20MIMO_Ant3_7015



11BE20MIMO_Ant4_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_7015



11BE20MIMO_Ant6_7015



11BE20MIMO_Ant3_7115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_7115



11BE20MIMO_Ant5_7115



11BE20MIMO_Ant6_7115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6125



11BE40MIMO_Ant4_6125



11BE40MIMO_Ant5_6125

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6125



11BE40MIMO_Ant3_6285



11BE40MIMO_Ant4_6285

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6285



11BE40MIMO_Ant6_6285



11BE40MIMO_Ant3_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6405



11BE40MIMO_Ant5_6405



11BE40MIMO_Ant6_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6445



11BE40MIMO_Ant4_6445



11BE40MIMO_Ant5_6445

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6445



11BE40MIMO_Ant3_6485



11BE40MIMO_Ant4_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.