




11BE20MIMO_Ant5_6275




11BE20MIMO_Ant6_6275




11BE20MIMO_Ant3_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6415




11BE20MIMO_Ant5_6415




11BE20MIMO_Ant6_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6435




11BE20MIMO_Ant4_6435




11BE20MIMO_Ant5_6435


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6435




11BE20MIMO_Ant3_6475




11BE20MIMO_Ant4_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6475




11BE20MIMO_Ant6_6475




11BE20MIMO_Ant3_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6515




11BE20MIMO_Ant5_6515




11BE20MIMO_Ant6_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6535




11BE20MIMO_Ant4_6535




11BE20MIMO_Ant5_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6535




11BE20MIMO_Ant3_6715




11BE20MIMO_Ant4_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6715




11BE20MIMO_Ant6_6715




11BE20MIMO_Ant3_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6875




11BE20MIMO_Ant5_6875




11BE20MIMO_Ant6_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6895




11BE20MIMO_Ant4_6895




11BE20MIMO_Ant5_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6895




11BE20MIMO_Ant3_7015




11BE20MIMO_Ant4_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_7015




11BE20MIMO_Ant6_7015




11BE20MIMO_Ant3_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_7115




11BE20MIMO_Ant5_7115




11BE20MIMO_Ant6_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6125




11BE40MIMO_Ant4_6125




11BE40MIMO_Ant5_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6125




11BE40MIMO_Ant3_6285




11BE40MIMO_Ant4_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6285




11BE40MIMO_Ant6_6285




11BE40MIMO_Ant3_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6405




11BE40MIMO_Ant5_6405




11BE40MIMO_Ant6_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6445




11BE40MIMO_Ant4_6445




11BE40MIMO_Ant5_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6445




11BE40MIMO_Ant3_6485




11BE40MIMO_Ant4_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6485




11BE40MIMO_Ant6_6485




11BE40MIMO_Ant3_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6525



11BE40MIMO_Ant5_6525



11BE40MIMO_Ant6_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.