




11BE40MIMO_Ant3_6565




11BE40MIMO_Ant4_6565




11BE40MIMO_Ant5_6565


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6565




11BE40MIMO_Ant3_6685




11BE40MIMO_Ant4_6685


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6685




11BE40MIMO_Ant6_6685




11BE40MIMO_Ant3_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6845




11BE40MIMO_Ant5_6845




11BE40MIMO_Ant6_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6885




11BE40MIMO_Ant4_6885




11BE40MIMO_Ant5_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6885




11BE40MIMO_Ant3_7005




11BE40MIMO_Ant4_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_7005




11BE40MIMO_Ant6_7005




11BE40MIMO_Ant3_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_7085




11BE40MIMO_Ant5_7085




11BE40MIMO_Ant6_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_6145




11BE80MIMO_Ant4_6145




11BE80MIMO_Ant5_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_6145




11BE80MIMO_Ant3_6225




11BE80MIMO_Ant4_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6225




11BE80MIMO_Ant6_6225




11BE80MIMO_Ant3_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_6385




11BE80MIMO_Ant5_6385




11BE80MIMO_Ant6_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_6465




11BE80MIMO_Ant4_6465




11BE80MIMO_Ant5_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_6465




11BE80MIMO_Ant3_6545




11BE80MIMO_Ant4_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6545




11BE80MIMO_Ant6_6545




11BE80MIMO_Ant3_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_6705




11BE80MIMO_Ant5_6705




11BE80MIMO_Ant6_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_6865




11BE80MIMO_Ant4_6865




11BE80MIMO_Ant5_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_6865




11BE80MIMO_Ant3_6945




11BE80MIMO_Ant4_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6945




11BE80MIMO_Ant6_6945




11BE80MIMO_Ant3_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_7025




11BE80MIMO_Ant5_7025




11BE80MIMO_Ant6_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant3_6185




11BE160MIMO_Ant4_6185




11BE160MIMO_Ant5_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant6_6185



11BE160MIMO_Ant3_6345



11BE160MIMO_Ant4_6345

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.