




11AX20MIMO_Ant1_6755




11AX20MIMO_Ant2_6755




11AX20MIMO_Ant1_6815


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6815




11AX20MIMO_Ant1_6875




11AX20MIMO_Ant2_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6895




11AX20MIMO_Ant2_6895




11AX20MIMO_Ant1_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_7015




11AX20MIMO_Ant1_7095




11AX20MIMO_Ant2_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant3_6125




11AX40MIMO_Ant4_6125




11AX40MIMO_Ant3_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_6285




11AX40MIMO_Ant3_6405




11AX40MIMO_Ant4_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6765




11AX40MIMO_Ant2_6765




11AX40MIMO_Ant1_6805


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6805




11AX40MIMO_Ant1_6845




11AX40MIMO_Ant2_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6885




11AX40MIMO_Ant2_6885




11AX40MIMO_Ant1_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_7005




11AX40MIMO_Ant1_7085




11AX40MIMO_Ant2_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant3_6145




11AX80MIMO_Ant4_6145




11AX80MIMO_Ant3_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6225




11AX80MIMO_Ant3_6385




11AX80MIMO_Ant4_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6785




11AX80MIMO_Ant2_6785




11AX80MIMO_Ant1_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6865




11AX80MIMO_Ant1_6945




11AX80MIMO_Ant2_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_7025




11AX80MIMO_Ant2_7025




11AX160MIMO_Ant3_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant4_6185




11AX160MIMO_Ant3_6345




11AX160MIMO_Ant4_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant1_6825




11AX160MIMO_Ant2_6825




11AX160MIMO_Ant1_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant2_6985




11BE20MIMO_Ant3_6115




11BE20MIMO_Ant4_6115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_6275




11BE20MIMO_Ant4_6275




11BE20MIMO_Ant3_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6415




11BE20MIMO_Ant1_6755




11BE20MIMO_Ant2_6755


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_6815




11BE20MIMO_Ant2_6815




11BE20MIMO_Ant1_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6875




11BE20MIMO_Ant1_6895




11BE20MIMO_Ant2_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_7015




11BE20MIMO_Ant2_7015




11BE20MIMO_Ant1_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_7095




11BE40MIMO_Ant3_6125




11BE40MIMO_Ant4_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_6285




11BE40MIMO_Ant4_6285




11BE40MIMO_Ant3_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6405



11BE40MIMO_Ant1_6765



11BE40MIMO_Ant2_6765

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.