




11AX80MIMO_Ant7_6545




11AX80MIMO_Ant8_6545




11AX80MIMO_Ant5_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6705




11AX80MIMO_Ant7_6705




11AX80MIMO_Ant8_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6865




11AX80MIMO_Ant6_6865




11AX80MIMO_Ant7_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6865




11AX80MIMO_Ant5_6945




11AX80MIMO_Ant6_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6945




11AX80MIMO_Ant8_6945




11AX80MIMO_Ant5_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_7025




11AX80MIMO_Ant7_7025




11AX80MIMO_Ant8_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6185




11AX160MIMO_Ant6_6185




11AX160MIMO_Ant7_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6185




11AX160MIMO_Ant5_6345




11AX160MIMO_Ant6_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6345




11AX160MIMO_Ant8_6345




11AX160MIMO_Ant5_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6505




11AX160MIMO_Ant7_6505




11AX160MIMO_Ant8_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6665




11AX160MIMO_Ant6_6665




11AX160MIMO_Ant7_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6665




11AX160MIMO_Ant5_6825




11AX160MIMO_Ant6_6825


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6825




11AX160MIMO_Ant8_6825




11AX160MIMO_Ant5_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6985




11AX160MIMO_Ant7_6985




11AX160MIMO_Ant8_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6115




11BE20MIMO_Ant6_6115




11BE20MIMO_Ant7_6115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6115




11BE20MIMO_Ant5_6275




11BE20MIMO_Ant6_6275


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_6275




11BE20MIMO_Ant8_6275




11BE20MIMO_Ant5_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6415




11BE20MIMO_Ant7_6415




11BE20MIMO_Ant8_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6435




11BE20MIMO_Ant6_6435




11BE20MIMO_Ant7_6435


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6435



11BE20MIMO_Ant5_6475



11BE20MIMO_Ant6_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.