




11AX20MIMO_Ant8_6435




11AX20MIMO_Ant5_6475




11AX20MIMO_Ant6_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_6475




11AX20MIMO_Ant8_6475




11AX20MIMO_Ant5_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_6515




11AX20MIMO_Ant7_6515




11AX20MIMO_Ant8_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6535




11AX20MIMO_Ant6_6535




11AX20MIMO_Ant7_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6535




11AX20MIMO_Ant5_6715




11AX20MIMO_Ant6_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_6715




11AX20MIMO_Ant8_6715




11AX20MIMO_Ant5_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_6875




11AX20MIMO_Ant7_6875




11AX20MIMO_Ant8_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6895




11AX20MIMO_Ant6_6895




11AX20MIMO_Ant7_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6895




11AX20MIMO_Ant5_7015




11AX20MIMO_Ant6_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_7015




11AX20MIMO_Ant8_7015




11AX20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_7095




11AX20MIMO_Ant7_7095




11AX20MIMO_Ant8_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_7115




11AX20MIMO_Ant6_7115




11AX20MIMO_Ant7_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_7115




11AX40MIMO_Ant5_6125




11AX40MIMO_Ant6_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6125




11AX40MIMO_Ant8_6125




11AX40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6285




11AX40MIMO_Ant7_6285




11AX40MIMO_Ant8_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6405




11AX40MIMO_Ant6_6405




11AX40MIMO_Ant7_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_6405




11AX40MIMO_Ant5_6445




11AX40MIMO_Ant6_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6445




11AX40MIMO_Ant8_6445




11AX40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6485




11AX40MIMO_Ant7_6485




11AX40MIMO_Ant8_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6525




11AX40MIMO_Ant6_6525




11AX40MIMO_Ant7_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_6525




11AX40MIMO_Ant5_6725




11AX40MIMO_Ant6_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6725




11AX40MIMO_Ant8_6725




11AX40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6845




11AX40MIMO_Ant7_6845




11AX40MIMO_Ant8_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6885



11AX40MIMO_Ant6_6885



11AX40MIMO_Ant7_6885

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.