




11AX40MIMO_Ant8_6885




11AX40MIMO_Ant5_7005




11AX40MIMO_Ant6_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_7005




11AX40MIMO_Ant8_7005




11AX40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_7085




11AX40MIMO_Ant7_7085




11AX40MIMO_Ant8_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6145




11AX80MIMO_Ant6_6145




11AX80MIMO_Ant7_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6145




11AX80MIMO_Ant5_6255




11AX80MIMO_Ant6_6255


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6255




11AX80MIMO_Ant8_6255




11AX80MIMO_Ant5_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6385




11AX80MIMO_Ant7_6385




11AX80MIMO_Ant8_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6465




11AX80MIMO_Ant6_6465




11AX80MIMO_Ant7_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6465




11AX80MIMO_Ant5_6545




11AX80MIMO_Ant6_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6545




11AX80MIMO_Ant8_6545




11AX80MIMO_Ant5_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6705




11AX80MIMO_Ant7_6705




11AX80MIMO_Ant8_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6865




11AX80MIMO_Ant6_6865




11AX80MIMO_Ant7_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6865




11AX80MIMO_Ant5_6945




11AX80MIMO_Ant6_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6945




11AX80MIMO_Ant8_6945




11AX80MIMO_Ant5_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_7025




11AX80MIMO_Ant7_7025




11AX80MIMO_Ant8_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6185




11AX160MIMO_Ant6_6185




11AX160MIMO_Ant7_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6185




11AX160MIMO_Ant5_6345




11AX160MIMO_Ant6_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6345




11AX160MIMO_Ant8_6345




11AX160MIMO_Ant5_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6505



11AX160MIMO_Ant7_6505




11AX160MIMO_Ant8_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6665




11AX160MIMO_Ant6_6665




11AX160MIMO_Ant7_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6665




11AX160MIMO_Ant5_6825




11AX160MIMO_Ant6_6825


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant7_6825




11AX160MIMO_Ant8_6825




11AX160MIMO_Ant5_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6985




11AX160MIMO_Ant7_6985




11AX160MIMO_Ant8_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6115



11BE20MIMO_Ant6_6115



11BE20MIMO_Ant7_6115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.