




11BE20MIMO_Ant8_6115




11BE20MIMO_Ant5_6275




11BE20MIMO_Ant6_6275


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_6275




11BE20MIMO_Ant8_6275




11BE20MIMO_Ant5_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6415




11BE20MIMO_Ant7_6415




11BE20MIMO_Ant8_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6435




11BE20MIMO_Ant6_6435




11BE20MIMO_Ant7_6435


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6435




11BE20MIMO_Ant5_6475




11BE20MIMO_Ant6_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_6475




11BE20MIMO_Ant8_6475




11BE20MIMO_Ant5_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6515




11BE20MIMO_Ant7_6515




11BE20MIMO_Ant8_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6535




11BE20MIMO_Ant6_6535




11BE20MIMO_Ant7_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6535




11BE20MIMO_Ant5_6715




11BE20MIMO_Ant6_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_6715




11BE20MIMO_Ant8_6715




11BE20MIMO_Ant5_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6875




11BE20MIMO_Ant7_6875




11BE20MIMO_Ant8_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6895




11BE20MIMO_Ant6_6895




11BE20MIMO_Ant7_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6895




11BE20MIMO_Ant5_7015




11BE20MIMO_Ant6_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_7015




11BE20MIMO_Ant8_7015




11BE20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_7095




11BE20MIMO_Ant7_7095




11BE20MIMO_Ant8_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_7115




11BE20MIMO_Ant6_7115




11BE20MIMO_Ant7_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_7115




11BE40MIMO_Ant5_6125




11BE40MIMO_Ant6_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6125




11BE40MIMO_Ant8_6125




11BE40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6285




11BE40MIMO_Ant7_6285




11BE40MIMO_Ant8_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6405




11BE40MIMO_Ant6_6405




11BE40MIMO_Ant7_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6405




11BE40MIMO_Ant5_6445




11BE40MIMO_Ant6_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6445




11BE40MIMO_Ant8_6445




11BE40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6485



11BE40MIMO_Ant7_6485



11BE40MIMO_Ant8_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.