




11BE40MIMO_Ant5_6525




11BE40MIMO_Ant6_6525




11BE40MIMO_Ant7_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6525




11BE40MIMO_Ant5_6725




11BE40MIMO_Ant6_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6725




11BE40MIMO_Ant8_6725




11BE40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6845




11BE40MIMO_Ant7_6845




11BE40MIMO_Ant8_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6885




11BE40MIMO_Ant6_6885




11BE40MIMO_Ant7_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6885




11BE40MIMO_Ant5_7005




11BE40MIMO_Ant6_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_7005




11BE40MIMO_Ant8_7005




11BE40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_7085




11BE40MIMO_Ant7_7085




11BE40MIMO_Ant8_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6145




11BE80MIMO_Ant6_6145




11BE80MIMO_Ant7_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant8_6145




11BE80MIMO_Ant5_6225




11BE80MIMO_Ant6_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant7_6225




11BE80MIMO_Ant8_6225




11BE80MIMO_Ant5_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_6385




11BE80MIMO_Ant7_6385




11BE80MIMO_Ant8_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6465




11BE80MIMO_Ant6_6465




11BE80MIMO_Ant7_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant8_6465




11BE80MIMO_Ant5_6545




11BE80MIMO_Ant6_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant7_6545




11BE80MIMO_Ant8_6545




11BE80MIMO_Ant5_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_6705




11BE80MIMO_Ant7_6705




11BE80MIMO_Ant8_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6865




11BE80MIMO_Ant6_6865




11BE80MIMO_Ant7_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant8_6865




11BE80MIMO_Ant5_6945




11BE80MIMO_Ant6_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant7_6945




11BE80MIMO_Ant8_6945




11BE80MIMO_Ant5_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant6_7025




11BE80MIMO_Ant7_7025




11BE80MIMO_Ant8_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant5_6185




11BE160MIMO_Ant6_6185




11BE160MIMO_Ant7_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant8_6185




11BE160MIMO_Ant5_6345




11BE160MIMO_Ant6_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant7_6345




11BE160MIMO_Ant8_6345




11BE160MIMO_Ant5_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant6_6505



11BE160MIMO_Ant7_6505



11BE160MIMO_Ant8_6505

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.