




11BE20MIMO_Ant6_6875




11BE20MIMO_Ant7_6875




11BE20MIMO_Ant8_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6895




11BE20MIMO_Ant6_6895




11BE20MIMO_Ant7_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6895




11BE20MIMO_Ant5_7015




11BE20MIMO_Ant6_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant7_7015




11BE20MIMO_Ant8_7015




11BE20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_7095




11BE20MIMO_Ant7_7095




11BE20MIMO_Ant8_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_7115




11BE20MIMO_Ant6_7115




11BE20MIMO_Ant7_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_7115




11BE40MIMO_Ant5_6125




11BE40MIMO_Ant6_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6125




11BE40MIMO_Ant8_6125




11BE40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6285




11BE40MIMO_Ant7_6285




11BE40MIMO_Ant8_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6405




11BE40MIMO_Ant6_6405




11BE40MIMO_Ant7_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6405




11BE40MIMO_Ant5_6445




11BE40MIMO_Ant6_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6445




11BE40MIMO_Ant8_6445




11BE40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6485




11BE40MIMO_Ant7_6485




11BE40MIMO_Ant8_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6525




11BE40MIMO_Ant6_6525




11BE40MIMO_Ant7_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6525




11BE40MIMO_Ant5_6725




11BE40MIMO_Ant6_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_6725




11BE40MIMO_Ant8_6725




11BE40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_6845




11BE40MIMO_Ant7_6845




11BE40MIMO_Ant8_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6885




11BE40MIMO_Ant6_6885




11BE40MIMO_Ant7_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6885




11BE40MIMO_Ant5_7005




11BE40MIMO_Ant6_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant7_7005




11BE40MIMO_Ant8_7005




11BE40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant6_7085




11BE40MIMO_Ant7_7085




11BE40MIMO_Ant8_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6145




11BE80MIMO_Ant6_6145




11BE80MIMO_Ant7_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant8_6145




11BE80MIMO_Ant5_6225




11BE80MIMO_Ant6_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant7_6225



11BE80MIMO_Ant8_6225



11BE80MIMO_Ant5_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.