




11AX20MIMO_Ant5_6535




11AX20MIMO_Ant5_6715




11AX20MIMO_Ant5_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6895




11AX20MIMO_Ant5_7015




11AX20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_7115




11AX40MIMO_Ant5_6125




11AX40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6405




11AX40MIMO_Ant5_6445




11AX40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6525




11AX40MIMO_Ant5_6725




11AX40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6885




11AX40MIMO_Ant5_7005




11AX40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6145




11AX80MIMO_Ant5_6225




11AX80MIMO_Ant5_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6465




11AX80MIMO_Ant5_6545




11AX80MIMO_Ant5_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6865




11AX80MIMO_Ant5_6945




11AX80MIMO_Ant5_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6185




11AX160MIMO_Ant5_6345




11AX160MIMO_Ant5_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant5_6665




11AX160MIMO_Ant5_6825




11AX160MIMO_Ant5_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6115




11BE20MIMO_Ant5_6275




11BE20MIMO_Ant5_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6435




11BE20MIMO_Ant5_6475




11BE20MIMO_Ant5_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6535




11BE20MIMO_Ant5_6715




11BE20MIMO_Ant5_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_6895




11BE20MIMO_Ant5_7015




11BE20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant5_7115




11BE40MIMO_Ant5_6125




11BE40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6405




11BE40MIMO_Ant5_6445




11BE40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6525




11BE40MIMO_Ant5_6725




11BE40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant5_6885




11BE40MIMO_Ant5_7005




11BE40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6145




11BE80MIMO_Ant5_6225




11BE80MIMO_Ant5_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6465




11BE80MIMO_Ant5_6545




11BE80MIMO_Ant5_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant5_6865




11BE80MIMO_Ant5_6945




11BE80MIMO_Ant5_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant5_6185



11BE160MIMO_Ant5_6345



11BE160MIMO_Ant5_6505

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.