




11AX20-CDD_Ant1_6535




11AX20-CDD_Ant2_6535




11AX20-CDD_Ant3_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant4_6535




11AX20-CDD_Ant1_6695




11AX20-CDD_Ant2_6695


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_6695




11AX20-CDD_Ant4_6695




11AX20-CDD_Ant1_6855


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant2_6855




11AX20-CDD_Ant3_6855




11AX20-CDD_Ant4_6855


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant1_6875




11AX20-CDD_Ant2_6875




11AX20-CDD_Ant3_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant4_6875




11AX20-CDD_Ant1_6995




11AX20-CDD_Ant2_6995


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant3_6995




11AX20-CDD_Ant4_6995




11AX20-CDD_Ant1_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20-CDD_Ant2_7115




11AX20-CDD_Ant3_7115




11AX20-CDD_Ant4_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_5965




11AX40-CDD_Ant2_5965




11AX40-CDD_Ant3_5965


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant4_5965




11AX40-CDD_Ant1_6165




11AX40-CDD_Ant2_6165


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_6165




11AX40-CDD_Ant4_6165




11AX40-CDD_Ant1_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant2_6405




11AX40-CDD_Ant3_6405




11AX40-CDD_Ant4_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_6445




11AX40-CDD_Ant2_6445




11AX40-CDD_Ant3_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant4_6445




11AX40-CDD_Ant1_6485




11AX40-CDD_Ant2_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_6485




11AX40-CDD_Ant4_6485




11AX40-CDD_Ant1_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant2_6525




11AX40-CDD_Ant3_6525




11AX40-CDD_Ant4_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_6685




11AX40-CDD_Ant2_6685




11AX40-CDD_Ant3_6685


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant4_6685




11AX40-CDD_Ant1_6845




11AX40-CDD_Ant2_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_6845




11AX40-CDD_Ant4_6845




11AX40-CDD_Ant1_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant2_6885




11AX40-CDD_Ant3_6885




11AX40-CDD_Ant4_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant1_6965




11AX40-CDD_Ant2_6965




11AX40-CDD_Ant3_6965


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant4_6965




11AX40-CDD_Ant1_7085




11AX40-CDD_Ant2_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40-CDD_Ant3_7085




11AX40-CDD_Ant4_7085




11AX80-CDD_Ant1_5985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant2_5985




11AX80-CDD_Ant3_5985




11AX80-CDD_Ant4_5985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant1_6145




11AX80-CDD_Ant2_6145




11AX80-CDD_Ant3_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant4_6145




11AX80-CDD_Ant1_6385




11AX80-CDD_Ant2_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant3_6385




11AX80-CDD_Ant4_6385




11AX80-CDD_Ant1_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant2_6465




11AX80-CDD_Ant3_6465




11AX80-CDD_Ant4_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant1_6545




11AX80-CDD_Ant2_6545




11AX80-CDD_Ant3_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant4_6545




11AX80-CDD_Ant1_6705




11AX80-CDD_Ant2_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant3_6705




11AX80-CDD_Ant4_6705




11AX80-CDD_Ant1_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant2_6865




11AX80-CDD_Ant3_6865




11AX80-CDD_Ant4_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant1_6945




11AX80-CDD_Ant2_6945




11AX80-CDD_Ant3_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant4_6945




11AX80-CDD_Ant1_7025




11AX80-CDD_Ant2_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80-CDD_Ant3_7025




11AX80-CDD_Ant4_7025




11AX160-CDD_Ant1_6025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant2_6025




11AX160-CDD_Ant3_6025




11AX160-CDD_Ant4_6025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant1_6185




11AX160-CDD_Ant2_6185




11AX160-CDD_Ant3_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant4_6185




11AX160-CDD_Ant1_6345




11AX160-CDD_Ant2_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant3_6345




11AX160-CDD_Ant4_6345




11AX160-CDD_Ant1_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant2_6505




11AX160-CDD_Ant3_6505




11AX160-CDD_Ant4_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant1_6665




11AX160-CDD_Ant2_6665




11AX160-CDD_Ant3_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant4_6665




11AX160-CDD_Ant1_6825




11AX160-CDD_Ant2_6825


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant3_6825




11AX160-CDD_Ant4_6825




11AX160-CDD_Ant1_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160-CDD_Ant2_6985




11AX160-CDD_Ant3_6985




11AX160-CDD_Ant4_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant1_5955




11BE20-CDD_Ant2_5955




11BE20-CDD_Ant3_5955


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant4_5955




11BE20-CDD_Ant1_6175




11BE20-CDD_Ant2_6175


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant3_6175




11BE20-CDD_Ant4_6175




11BE20-CDD_Ant1_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant2_6415




11BE20-CDD_Ant3_6415




11BE20-CDD_Ant4_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant1_6435




11BE20-CDD_Ant2_6435




11BE20-CDD_Ant3_6435


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant4_6435




11BE20-CDD_Ant1_6475




11BE20-CDD_Ant2_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant3_6475




11BE20-CDD_Ant4_6475




11BE20-CDD_Ant1_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant2_6515




11BE20-CDD_Ant3_6515




11BE20-CDD_Ant4_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20-CDD_Ant1_6535



11BE20-CDD_Ant2_6535



11BE20-CDD_Ant3_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.