

11BE20MIMO_Ant2_5180



11BE20MIMO_Ant3_5180



11BE20MIMO_Ant4_5180

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5200



11BE20MIMO_Ant2_5200



11BE20MIMO_Ant3_5200

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_5200



11BE20MIMO_Ant1_5240



11BE20MIMO_Ant2_5240

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5240



11BE20MIMO_Ant4_5240



11BE20MIMO_Ant1_5500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_5500



11BE20MIMO_Ant3_5500



11BE20MIMO_Ant4_5500

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5580



11BE20MIMO_Ant2_5580



11BE20MIMO_Ant3_5580

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_5580



11BE20MIMO_Ant1_5700



11BE20MIMO_Ant2_5700

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5700



11BE20MIMO_Ant4_5700



11BE20MIMO_Ant1_5720

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_5720



11BE20MIMO_Ant3_5720



11BE20MIMO_Ant4_5720

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant1_5745



11BE20MIMO_Ant2_5745



11BE20MIMO_Ant3_5745

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_5745



11BE20MIMO_Ant1_5785



11BE20MIMO_Ant2_5785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant3_5785



11BE20MIMO_Ant4_5785



11BE20MIMO_Ant1_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_5825



11BE20MIMO_Ant3_5825



11BE20MIMO_Ant4_5825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_5190



11BE40MIMO_Ant2_5190



11BE40MIMO_Ant3_5190

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_5190



11BE40MIMO_Ant1_5230



11BE40MIMO_Ant2_5230

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_5230



11BE40MIMO_Ant4_5230



11BE40MIMO_Ant1_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant2_5510



11BE40MIMO_Ant3_5510



11BE40MIMO_Ant4_5510

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_5550



11BE40MIMO_Ant2_5550



11BE40MIMO_Ant3_5550

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_5550



11BE40MIMO_Ant1_5670



11BE40MIMO_Ant2_5670

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_5670



11BE40MIMO_Ant4_5670



11BE40MIMO_Ant1_5710

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant2_5710



11BE40MIMO_Ant3_5710



11BE40MIMO_Ant4_5710

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant1_5755



11BE40MIMO_Ant2_5755



11BE40MIMO_Ant3_5755

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_5755



11BE40MIMO_Ant1_5795



11BE40MIMO_Ant2_5795

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant3_5795



11BE40MIMO_Ant4_5795



11BE80MIMO_Ant1_5210

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant2_5210



11BE80MIMO_Ant3_5210



11BE80MIMO_Ant4_5210

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant1_5530



11BE80MIMO_Ant2_5530



11BE80MIMO_Ant3_5530

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_5530



11BE80MIMO_Ant1_5610



11BE80MIMO_Ant2_5610

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant3_5610



11BE80MIMO_Ant4_5610



11BE80MIMO_Ant1_5690

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant2_5690



11BE80MIMO_Ant3_5690



11BE80MIMO_Ant4_5690

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant1_5775



11BE80MIMO_Ant2_5775



11BE80MIMO_Ant3_5775

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE80MIMO_Ant4_5775



11BE160MIMO_Ant1_5250



11BE160MIMO_Ant2_5250

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant3_5250



11BE160MIMO_Ant4_5250



11BE160MIMO_Ant1_5570

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE160MIMO_Ant2_5570



11BE160MIMO_Ant3_5570



11BE160MIMO_Ant4_5570

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE240MIMO_Ant1_5610



11BE240MIMO_Ant2_5610



11BE240MIMO_Ant3_5610

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.