




11AX160MIMO_Ant2_6185




11AX160MIMO_Ant4_6185




11AX160MIMO_Ant6_6185


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6185




11AX160MIMO_Ant2_6345




11AX160MIMO_Ant4_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6345




11AX160MIMO_Ant8_6345




11AX160MIMO_Ant2_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant4_6505




11AX160MIMO_Ant6_6505




11AX160MIMO_Ant8_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant2_6665




11AX160MIMO_Ant4_6665




11AX160MIMO_Ant6_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6665




11AX160MIMO_Ant2_6825




11AX160MIMO_Ant4_6825


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6825




11AX160MIMO_Ant8_6825




11AX160MIMO_Ant2_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant4_6985




11AX160MIMO_Ant6_6985




11AX160MIMO_Ant8_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6115




11BE20MIMO_Ant4_6115




11BE20MIMO_Ant6_6115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6115




11BE20MIMO_Ant2_6275




11BE20MIMO_Ant4_6275


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6275




11BE20MIMO_Ant8_6275




11BE20MIMO_Ant2_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6415




11BE20MIMO_Ant6_6415




11BE20MIMO_Ant8_6415


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6435




11BE20MIMO_Ant4_6435




11BE20MIMO_Ant6_6435


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6435




11BE20MIMO_Ant2_6475




11BE20MIMO_Ant4_6475


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6475




11BE20MIMO_Ant8_6475




11BE20MIMO_Ant2_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6515




11BE20MIMO_Ant6_6515




11BE20MIMO_Ant8_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6535




11BE20MIMO_Ant4_6535




11BE20MIMO_Ant6_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6535




11BE20MIMO_Ant2_6715




11BE20MIMO_Ant4_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6715




11BE20MIMO_Ant8_6715




11BE20MIMO_Ant2_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6875




11BE20MIMO_Ant6_6875




11BE20MIMO_Ant8_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6895




11BE20MIMO_Ant4_6895




11BE20MIMO_Ant6_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6895




11BE20MIMO_Ant2_7015




11BE20MIMO_Ant4_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_7015



11BE20MIMO_Ant8_7015



11BE20MIMO_Ant2_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.