




11AX80MIMO_Ant6_6385




11AX80MIMO_Ant8_6385




11AX80MIMO_Ant2_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6465




11AX80MIMO_Ant6_6465



11AX80MIMO_Ant8_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6545




11AX80MIMO_Ant4_6545




11AX80MIMO_Ant6_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6545



11AX80MIMO_Ant2_6705




11AX80MIMO_Ant4_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6705




11AX80MIMO_Ant8_6705



11AX80MIMO_Ant2_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6865




11AX80MIMO_Ant6_6865




11AX80MIMO_Ant8_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6945




11AX80MIMO_Ant4_6945



11AX80MIMO_Ant6_6945


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6945



11AX80MIMO_Ant2_7025




11AX80MIMO_Ant4_7025


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_7025



11AX80MIMO_Ant8_7025




11AX160MIMO_Ant2_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant4_6185



11AX160MIMO_Ant6_6185




11AX160MIMO_Ant8_6185

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant2_6345



11AX160MIMO_Ant4_6345



11AX160MIMO_Ant6_6345


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6345



11AX160MIMO_Ant2_6505



11AX160MIMO_Ant4_6505


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6505




11AX160MIMO_Ant8_6505



11AX160MIMO_Ant2_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant4_6665



11AX160MIMO_Ant6_6665



11AX160MIMO_Ant8_6665


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant2_6825



11AX160MIMO_Ant4_6825



11AX160MIMO_Ant6_6825

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant8_6825



11AX160MIMO_Ant2_6985



11AX160MIMO_Ant4_6985


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX160MIMO_Ant6_6985



11AX160MIMO_Ant8_6985



11BE20MIMO_Ant2_6115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6115



11BE20MIMO_Ant6_6115



11BE20MIMO_Ant8_6115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.