11BE20MIMO_Ant2_6275



11BE20MIMO_Ant4_6275



11BE20MIMO_Ant6_6275

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6275



11BE20MIMO_Ant2_6415



11BE20MIMO_Ant4_6415

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6415



11BE20MIMO_Ant8_6415



11BE20MIMO_Ant2_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6435



11BE20MIMO_Ant6_6435



11BE20MIMO_Ant8_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6475



11BE20MIMO_Ant4_6475



11BE20MIMO_Ant6_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11BE20MIMO_Ant8_6475



11BE20MIMO_Ant2_6515



11BE20MIMO_Ant4_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6515



11BE20MIMO_Ant8_6515



11BE20MIMO_Ant2_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6535



11BE20MIMO_Ant6_6535



11BE20MIMO_Ant8_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_6715



11BE20MIMO_Ant4_6715



11BE20MIMO_Ant6_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_6715



11BE20MIMO_Ant2_6875



11BE20MIMO_Ant4_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_6875



11BE20MIMO_Ant8_6875



11BE20MIMO_Ant2_6895

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant4_6895



11BE20MIMO_Ant6_6895



11BE20MIMO_Ant8_6895

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant2_7015



11BE20MIMO_Ant4_7015



11BE20MIMO_Ant6_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant8_7015



11BE20MIMO_Ant2_7095



11BE20MIMO_Ant4_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE20MIMO_Ant6_7095



11BE20MIMO_Ant8_7095



11BE40MIMO_Ant2_6125

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant4_6125



11BE40MIMO_Ant6_6125



11BE40MIMO_Ant8_6125

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant2_6285



11BE40MIMO_Ant4_6285



11BE40MIMO_Ant6_6285

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11BE40MIMO_Ant8_6285



11BE40MIMO_Ant2_6405



11BE40MIMO_Ant4_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.