11.2.2. Test Graphs



11AX20MIMO_Ant2_6115



11AX20MIMO_Ant4_6115



11AX20MIMO_Ant6_6115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6115



11AX20MIMO_Ant2_6275



11AX20MIMO_Ant4_6275

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_6275



11AX20MIMO_Ant8_6275



11AX20MIMO_Ant2_6415

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant4_6415



11AX20MIMO_Ant6_6415



11AX20MIMO_Ant8_6415

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6435



11AX20MIMO_Ant4_6435



11AX20MIMO_Ant6_6435

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6435



11AX20MIMO_Ant2_6475



11AX20MIMO_Ant4_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_6475



11AX20MIMO_Ant8_6475



11AX20MIMO_Ant2_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant4_6515



11AX20MIMO_Ant6_6515



11AX20MIMO_Ant8_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6535



11AX20MIMO_Ant4_6535



11AX20MIMO_Ant6_6535

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6535



11AX20MIMO_Ant2_6715



11AX20MIMO_Ant4_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_6715



11AX20MIMO_Ant8_6715



11AX20MIMO_Ant2_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant4_6875



11AX20MIMO_Ant6_6875



11AX20MIMO_Ant8_6875

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6895



11AX20MIMO_Ant4_6895



11AX20MIMO_Ant6_6895

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_6895



11AX20MIMO_Ant2_7015



11AX20MIMO_Ant4_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_7015



11AX20MIMO_Ant8_7015



11AX20MIMO_Ant2_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant4_7095



11AX20MIMO_Ant6_7095



11AX20MIMO_Ant8_7095

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6125



11AX40MIMO_Ant4_6125



11AX40MIMO_Ant6_6125

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_6125



11AX40MIMO_Ant2_6285



11AX40MIMO_Ant4_6285

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6285



11AX40MIMO_Ant8_6285



11AX40MIMO_Ant2_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_6405



11AX40MIMO_Ant6_6405



11AX40MIMO_Ant8_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.