




11AX40MIMO_Ant2_6445




11AX40MIMO_Ant4_6445




11AX40MIMO_Ant6_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_6445




11AX40MIMO_Ant2_6485




11AX40MIMO_Ant4_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6485




11AX40MIMO_Ant8_6485




11AX40MIMO_Ant2_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_6525




11AX40MIMO_Ant6_6525




11AX40MIMO_Ant8_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6725




11AX40MIMO_Ant4_6725




11AX40MIMO_Ant6_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_6725




11AX40MIMO_Ant2_6845




11AX40MIMO_Ant4_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_6845




11AX40MIMO_Ant8_6845




11AX40MIMO_Ant2_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant4_6885




11AX40MIMO_Ant6_6885




11AX40MIMO_Ant8_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_7005




11AX40MIMO_Ant4_7005




11AX40MIMO_Ant6_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant8_7005




11AX40MIMO_Ant2_7085




11AX40MIMO_Ant4_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant6_7085




11AX40MIMO_Ant8_7085




11AX80MIMO_Ant2_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6145




11AX80MIMO_Ant6_6145




11AX80MIMO_Ant8_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6225




11AX80MIMO_Ant4_6225




11AX80MIMO_Ant6_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6225




11AX80MIMO_Ant2_6385




11AX80MIMO_Ant4_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6385




11AX80MIMO_Ant8_6385




11AX80MIMO_Ant2_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6465




11AX80MIMO_Ant6_6465




11AX80MIMO_Ant8_6465


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6545




11AX80MIMO_Ant4_6545




11AX80MIMO_Ant6_6545


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant8_6545




11AX80MIMO_Ant2_6705




11AX80MIMO_Ant4_6705


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant6_6705




11AX80MIMO_Ant8_6705




11AX80MIMO_Ant2_6865


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant4_6865



11AX80MIMO_Ant6_6865



11AX80MIMO_Ant8_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.