




11B-CDD_Ant12_2412




11B-CDD_Ant14_2412




11B-CDD_Ant6_2417


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant8_2417




11B-CDD_Ant12_2417




11B-CDD_Ant14_2417


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant6_2437




11B-CDD_Ant8_2437




11B-CDD_Ant12_2437


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant14_2437




11B-CDD_Ant6_2457




11B-CDD_Ant8_2457


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant12_2457




11B-CDD_Ant14_2457




11B-CDD_Ant6_2462


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11B-CDD_Ant8_2462




11B-CDD_Ant12_2462




11B-CDD_Ant14_2462


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant6_2412




11G-CDD_Ant8_2412




11G-CDD_Ant12_2412


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant14_2412




11G-CDD_Ant6_2417




11G-CDD_Ant8_2417


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant12_2417




11G-CDD_Ant14_2417




11G-CDD_Ant6_2437


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant8_2437




11G-CDD_Ant12_2437




11G-CDD_Ant14_2437


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant6_2457




11G-CDD_Ant8_2457




11G-CDD_Ant12_2457


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant14_2457




11G-CDD_Ant6_2462




11G-CDD_Ant8_2462


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11G-CDD_Ant12_2462




11G-CDD_Ant14_2462




11AX20MIMO_Ant6_2412


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_2412




11AX20MIMO_Ant12_2412




11AX20MIMO_Ant14_2412


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_2417




11AX20MIMO_Ant8_2417




11AX20MIMO_Ant12_2417


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant14_2417




11AX20MIMO_Ant6_2437




11AX20MIMO_Ant8_2437


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant12_2437




11AX20MIMO_Ant14_2437




11AX20MIMO_Ant6_2457


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant8_2457




11AX20MIMO_Ant12_2457




11AX20MIMO_Ant14_2457


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant6_2462




11AX20MIMO_Ant8_2462




11AX20MIMO_Ant12_2462


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant14_2462



11AX40MIMO_Ant6_2422



11AX40MIMO_Ant8_2422

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.