




11AX20MIMO_Ant13_6895




11AX20MIMO_Ant5_7015




11AX20MIMO_Ant7_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant11_7015




11AX20MIMO_Ant13_7015




11AX20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_7095




11AX20MIMO_Ant11_7095




11AX20MIMO_Ant13_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_7115




11AX20MIMO_Ant7_7115




11AX20MIMO_Ant11_7115


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant13_7115




11AX40MIMO_Ant5_6125




11AX40MIMO_Ant7_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6125




11AX40MIMO_Ant13_6125




11AX40MIMO_Ant5_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6285




11AX40MIMO_Ant11_6285




11AX40MIMO_Ant13_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6405




11AX40MIMO_Ant7_6405




11AX40MIMO_Ant11_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6405




11AX40MIMO_Ant5_6445




11AX40MIMO_Ant7_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6445




11AX40MIMO_Ant13_6445




11AX40MIMO_Ant5_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6485




11AX40MIMO_Ant11_6485




11AX40MIMO_Ant13_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6525




11AX40MIMO_Ant7_6525




11AX40MIMO_Ant11_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6525




11AX40MIMO_Ant5_6725




11AX40MIMO_Ant7_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6725




11AX40MIMO_Ant13_6725




11AX40MIMO_Ant5_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6845




11AX40MIMO_Ant11_6845




11AX40MIMO_Ant13_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6885




11AX40MIMO_Ant7_6885




11AX40MIMO_Ant11_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6885




11AX40MIMO_Ant5_7005




11AX40MIMO_Ant7_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_7005




11AX40MIMO_Ant13_7005




11AX40MIMO_Ant5_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_7085




11AX40MIMO_Ant11_7085




11AX40MIMO_Ant13_7085


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant5_6145




11AX80MIMO_Ant7_6145




11AX80MIMO_Ant11_6145


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant13_6145




11AX80MIMO_Ant5_6225




11AX80MIMO_Ant7_6225


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant11_6225




11AX80MIMO_Ant13_6225




11AX80MIMO_Ant5_6385


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant7_6385



11AX80MIMO_Ant11_6385



11AX80MIMO_Ant13_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.