




11AX20MIMO_Ant7_6515




11AX20MIMO_Ant11_6515




11AX20MIMO_Ant13_6515


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6535




11AX20MIMO_Ant7_6535




11AX20MIMO_Ant11_6535


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant13_6535




11AX20MIMO_Ant5_6715




11AX20MIMO_Ant7_6715


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant11_6715




11AX20MIMO_Ant13_6715




11AX20MIMO_Ant5_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_6875




11AX20MIMO_Ant11_6875




11AX20MIMO_Ant13_6875


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant5_6895




11AX20MIMO_Ant7_6895




11AX20MIMO_Ant11_6895


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant13_6895




11AX20MIMO_Ant5_7015




11AX20MIMO_Ant7_7015


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant11_7015




11AX20MIMO_Ant13_7015




11AX20MIMO_Ant5_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant7_7095




11AX20MIMO_Ant11_7095




11AX20MIMO_Ant13_7095


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6125




11AX40MIMO_Ant7_6125




11AX40MIMO_Ant11_6125


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6125




11AX40MIMO_Ant5_6285




11AX40MIMO_Ant7_6285


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6285




11AX40MIMO_Ant13_6285




11AX40MIMO_Ant5_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6405




11AX40MIMO_Ant11_6405




11AX40MIMO_Ant13_6405


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6445




11AX40MIMO_Ant7_6445




11AX40MIMO_Ant11_6445


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6445




11AX40MIMO_Ant5_6485




11AX40MIMO_Ant7_6485


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6485




11AX40MIMO_Ant13_6485




11AX40MIMO_Ant5_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6525




11AX40MIMO_Ant11_6525




11AX40MIMO_Ant13_6525


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_6725




11AX40MIMO_Ant7_6725




11AX40MIMO_Ant11_6725


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_6725




11AX40MIMO_Ant5_6845




11AX40MIMO_Ant7_6845


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant11_6845




11AX40MIMO_Ant13_6845




11AX40MIMO_Ant5_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant7_6885




11AX40MIMO_Ant11_6885




11AX40MIMO_Ant13_6885


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant5_7005




11AX40MIMO_Ant7_7005




11AX40MIMO_Ant11_7005


This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant13_7005



11AX40MIMO_Ant5_7085



11AX40MIMO_Ant7_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.