

Band41_5MHz_QPSK_41215_1RB#0_30~1000_30~1000



Band41_5MHz_QPSK_41215_1RB#0_1000~20000_1000~20000



Band41_5MHz_QPSK_41215_1RB#0_20000~27000_20000~27000



Band41_5MHz_16QAM_41215_1RB#0_0.009~0.15_0.009~0.15



Band41_5MHz_16QAM_41215_1RB#0_0.15~30_0.15~30



Band41_5MHz_16QAM_41215_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_5MHz_16QAM_41215_1RB#0_1000~20000_1000~20000



Band41_5MHz_16QAM_41215_1RB#0_20000~27000_20000~27000



Band41_5MHz_QPSK_41215_1RB#24_0.009~0.15_0.009~0.15



Band41_5MHz_QPSK_41215_1RB#24_0.15~30_0.15~30



Band41_5MHz_QPSK_41215_1RB#24_30~1000_30~1000



Band41_5MHz_QPSK_41215_1RB#24_1000~20000_1000~20000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_5MHz_QPSK_41215_1RB#24_20000~27000_20000~27000



Band41_5MHz_16QAM_41215_1RB#24_0.009~0.15_0.009~0.15



Band41_5MHz_16QAM_41215_1RB#24_0.15~30_0.15~30



Band41_5MHz_16QAM_41215_1RB#24_30~1000_30~1000



Band41_5MHz_16QAM_41215_1RB#24_1000~20000_1000~20000



Band41_5MHz_16QAM_41215_1RB#24_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_5MHz_QPSK_41215_25RB#0_0.009~0.15_0.009~0.15



Band41_5MHz_QPSK_41215_25RB#0_0.15~30_0.15~30



Band41_5MHz_QPSK_41215_25RB#0_30~1000_30~1000



Band41_5MHz_QPSK_41215_25RB#0_1000~20000_1000~20000



Band41_5MHz_QPSK_41215_25RB#0_20000~27000_20000~27000



Band41_5MHz_16QAM_41215_25RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_5MHz_16QAM_41215_25RB#0_0.15~30_0.15~30



Band41_5MHz_16QAM_41215_25RB#0_30~1000_30~1000



Band41_5MHz_16QAM_41215_25RB#0_1000~20000_1000~20000



Band41_5MHz_16QAM_41215_25RB#0_20000~27000_20000~27000



Band41_10MHz_QPSK_40090_1RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40090_1RB#0_0.15~30_0.15~30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40090_1RB#0_30~1000_30~1000



Band41_10MHz_QPSK_40090_1RB#0_1000~20000_1000~20000



Band41_10MHz_QPSK_40090_1RB#0_20000~27000_20000~27000



Band41_10MHz_16QAM_40090_1RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_16QAM_40090_1RB#0_0.15~30_0.15~30



Band41_10MHz_16QAM_40090_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_16QAM_40090_1RB#0_1000~20000_1000~20000



Band41_10MHz_16QAM_40090_1RB#0_20000~27000_20000~27000



Band41_10MHz_QPSK_40090_1RB#49_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40090_1RB#49_0.15~30_0.15~30



Band41_10MHz_QPSK_40090_1RB#49_30~1000_30~1000



Band41_10MHz_QPSK_40090_1RB#49_1000~20000_1000~20000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40090_1RB#49_20000~27000_20000~27000



Band41_10MHz_16QAM_40090_1RB#49_0.009~0.15_0.009~0.15



Band41_10MHz_16QAM_40090_1RB#49_0.15~30_0.15~30



Band41_10MHz_16QAM_40090_1RB#49_30~1000_30~1000



Band41_10MHz_16QAM_40090_1RB#49_1000~20000_1000~20000



Band41_10MHz_16QAM_40090_1RB#49_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40090_50RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40090_50RB#0_0.15~30_0.15~30



Band41_10MHz_QPSK_40090_50RB#0_30~1000_30~1000



Band41_10MHz_QPSK_40090_50RB#0_1000~20000_1000~20000



Band41_10MHz_QPSK_40090_50RB#0_20000~27000_20000~27000



Band41_10MHz_16QAM_40090_50RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_16QAM_40090_50RB#0_0.15~30_0.15~30



Band41_10MHz_16QAM_40090_50RB#0_30~1000_30~1000



Band41_10MHz_16QAM_40090_50RB#0_1000~20000_1000~20000



Band41_10MHz_16QAM_40090_50RB#0_20000~27000_20000~27000



Band41_10MHz_QPSK_40590_1RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40590_1RB#0_0.15~30_0.15~30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40590_1RB#0_30~1000_30~1000



Band41_10MHz_QPSK_40590_1RB#0_1000~20000_1000~20000



Band41_10MHz_QPSK_40590_1RB#0_20000~27000_20000~27000



Band41_10MHz_16QAM_40590_1RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_16QAM_40590_1RB#0_0.15~30_0.15~30



Band41_10MHz_16QAM_40590_1RB#0_30~1000_30~1000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_16QAM_40590_1RB#0_1000~20000_1000~20000



Band41_10MHz_16QAM_40590_1RB#0_20000~27000_20000~27000



Band41_10MHz_QPSK_40590_1RB#49_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40590_1RB#49_0.15~30_0.15~30



Band41_10MHz_QPSK_40590_1RB#49_30~1000_30~1000



Band41_10MHz_QPSK_40590_1RB#49_1000~20000_1000~20000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40590_1RB#49_20000~27000_20000~27000



Band41_10MHz_16QAM_40590_1RB#49_0.009~0.15_0.009~0.15



Band41_10MHz_16QAM_40590_1RB#49_0.15~30_0.15~30



Band41_10MHz_16QAM_40590_1RB#49_30~1000_30~1000



Band41_10MHz_16QAM_40590_1RB#49_1000~20000_1000~20000



Band41_10MHz_16QAM_40590_1RB#49_20000~27000_20000~27000

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_QPSK_40590_50RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_40590_50RB#0_0.15~30_0.15~30



Band41_10MHz_QPSK_40590_50RB#0_30~1000_30~1000



Band41_10MHz_QPSK_40590_50RB#0_1000~20000_1000~20000



Band41_10MHz_QPSK_40590_50RB#0_20000~27000_20000~27000



Band41_10MHz_16QAM_40590_50RB#0_0.009~0.15_0.009~0.15

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.



Band41_10MHz_16QAM_40590_50RB#0_0.15~30_0.15~30



Band41_10MHz_16QAM_40590_50RB#0_30~1000_30~1000



Band41_10MHz_16QAM_40590_50RB#0_1000~20000_1000~20000



Band41_10MHz_16QAM_40590_50RB#0_20000~27000_20000~27000



Band41_10MHz_QPSK_41190_1RB#0_0.009~0.15_0.009~0.15



Band41_10MHz_QPSK_41190_1RB#0_0.15~30_0.15~30

Any report having not been signed by authorized approver, or having been altered without authorization, or having not been stamped by the "Dedicated Testing/Inspection Stamp" is deemed to be invalid. Copying or excerpting portion of, or altering the content of the report is not permitted without the written authorization of AGC. The test results presented in the report apply only to the tested sample. Any objections to report issued by AGC should be submitted to AGC within 15days after the issuance of the test report. Further enquiry of validity or verification of the test report should be addressed to AGC by agc01@agccert.com.