



Band 26 5 MHz High QPSK RB15#0 1(30MHz-1GHz)




Date: 25.APR.2022 15:08:54

Band 26_5 MHz_High_QPSK_RB15#0_2(1GHz-9GHz)




Date: 25.APR.2022 15:37:53

Band 26 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 25.APR.2022 15:26:38

Band 26 10 MHz Low QPSK RB50#0 2(1GHz-9GHz)




Date: 25.APR.2022 15:35:55

Band 26_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 25.APR.2022 15:24:59

Band 26_10 MHz_Middle_QPSK_RB50#0_2(1GHz-9GHz)




Date: 25.APR.2022 15:35:38

Band 26 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 25.APR.2022 15:23:14

Band 26 10 MHz High QPSK RB50#0 2(1GHz-9GHz)




Date: 25.APR.2022 15:35:19

Band 26 15 MHz Low QPSK RB75#0 1(30MHz-1GHz)




Date: 25.APR.2022 15:29:03

Band 26_15 MHz_Low_QPSK_RB75#0_2(1GHz-9GHz)




Date: 25.APR.2022 15:33:52

Band 26_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.APR.2022 15:30:00

Band 26_15 MHz_Middle_QPSK_RB75#0_2(1GHz-9GHz)




Date: 25.APR.2022 15:33:34

Band 26_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.APR.2022 15:32:22


Band 26_15 MHz_High_QPSK_RB75#0_2(1GHz-9GHz)



Date: 25.APR.2022 15:33:14




Date: 26.APR.2022 11:53:32




Date: 26.APR.2022 11:29:00

Band 41 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 26.APR.2022 11:54:26

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:30:48

Band 41 5 MHz High QPSK RB25#0 1(30MHz-1GHz)




Date: 26.APR.2022 11:52:22

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:29:49

Band 41 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 26.APR.2022 11:55:54

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:34:45

Band 41 10 MHz Middle QPSK RB50#0 1(30MHz-1GHz)




Date: 26.APR.2022 12:59:41

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:38:02

Band 41 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 26.APR.2022 11:55:15

Band 41 10 MHz High QPSK RB50#0 2(1GHz-27GHz)




Date: 26.APR.2022 11:36:22

Band 41 15 MHz Low QPSK RB75#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:01:16

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:38:56

Band 41 15 MHz Middle QPSK RB75#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:02:00

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:43:55

Band 41 15 MHz High QPSK RB75#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:00:39

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:41:49

Band 41 20 MHz Low QPSK RB100#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:03:21

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:49:07

Band 41 20 MHz Middle QPSK RB100#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:03:56

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-27GHz)




Date: 26.APR.2022 11:47:10

Band 41 20 MHz High QPSK RB100#0 1(30MHz-1GHz)




Date: 26.APR.2022 13:02:38


Band 41 20 MHz High QPSK RB100#0 2(1GHz-27GHz)



Date: 26.APR.2022 11:50:30




Date: 25.APR.2022 19:07:15




Date: 25.APR.2022 18:15:59

Band 66 1.4 MHz Middle QPSK RB6#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:07:03

Band 66_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:17:05

Band 66 1.4 MHz High QPSK RB6#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:05:28

Band 66_1.4 MHz_High_QPSK_RB6#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:13:57

Band 66 3 MHz Low QPSK RB15#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:02:35

Band 66_3 MHz_Low_QPSK_RB15#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:23:17

Band 66 3 MHz Middle QPSK RB15#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:01:00

Band 66_3 MHz_Middle_QPSK_RB15#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:19:59

Band 66 3 MHz High QPSK RB15#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:01:51

Band 66 3 MHz High QPSK RB15#0 2(1GHz-18GHz)




Date: 25.APR.2022 18:21:31

Band 66 5 MHz Low QPSK RB25#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:59:40

Band 66_5 MHz_Low_QPSK_RB25#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:27:25

Band 66 5 MHz Middle QPSK RB25#0 1(30MHz-1GHz)




Date: 25.APR.2022 19:00:43


Band 66_5 MHz_Middle_QPSK_RB25#0_2(1GHz-18GHz)



Date: 25.APR.2022 18:28:29




Date: 25.APR.2022 18:55:43




Date: 25.APR.2022 18:31:20

Band 66 10 MHz Low QPSK RB50#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:56:52

Band 66_10 MHz_Low_QPSK_RB50#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:32:34

Band 66 10 MHz Middle QPSK RB50#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:57:37

Band 66_10 MHz_Middle_QPSK_RB50#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:33:33

Band 66 10 MHz High QPSK RB50#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:55:43

Band 66_10 MHz_High_QPSK_RB50#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:31:20

Band 66 15 MHz Low QPSK RB75#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:54:03

Band 66_15 MHz_Low_QPSK_RB75#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:43:01

Band 66_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.APR.2022 18:54:59

Band 66_15 MHz_Middle_QPSK_RB75#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:44:24

Band 66_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 25.APR.2022 18:53:02

Band 66_15 MHz_High_QPSK_RB75#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:39:24

Band 66 20 MHz Low QPSK RB100#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:52:00

Band 66_20 MHz_Low_QPSK_RB100#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:47:37

Band 66 20 MHz Middle QPSK RB100#0 1(30MHz-1GHz)




Date: 25.APR.2022 18:50:14

Band 66_20 MHz_Middle_QPSK_RB100#0_2(1GHz-18GHz)




Date: 25.APR.2022 18:49:06

Band 66 20 MHz High QPSK RB100#0 1(30MHz-1GHz)



Date: 25.APR.2022 18:51:40


Band 66_20 MHz_High_QPSK_RB100#0_2(1GHz-18GHz)



Date: 25.APR.2022 18:46:14


Please refer to following plots:

Band 2 1.4 MHz Low 16QAM RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:12:53


Band 2_1.4 MHz_Low_16QAM_RB6#0_2(1GHz-20GHz)



Date: 23.APR.2022 13:29:23




Date: 23.APR.2022 14:13:18




Date: 23.APR.2022 13:29:23

Band 2 1.4 MHz High 16QAM RB6#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:14:46

Band 2_1.4 MHz_High_16QAM_RB6#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:28:14

Band 2 3 MHz Low 16QAM RB15#0 1(30MHz-1GHz)




Date: 23. APR. 2022 14:09:50

Band 2_3 MHz_Low_16QAM_RB15#0_2(1GHz-20GHz)




Date: 23. APR. 2022 13:36:35

Band 2 3 MHz Middle 16QAM RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:11:00

Band 2_3 MHz_Middle_16QAM_RB15#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:32:26

Band 2 3 MHz High 16QAM RB15#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:11:21

Band 2_3 MHz_High_16QAM_RB15#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:34:16

Band 2 5 MHz Low 16QAM RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:06:47

Band 2 5 MHz Low 16QAM RB25#0 2(1GHz-20GHz)




Date: 23.APR.2022 13:42:14

Band 2 5 MHz Middle 16QAM RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:08:06

Band 2_5 MHz_Middle_16QAM_RB25#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:38:10

Band 2 5 MHz High 16QAM RB25#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:08:26

Band 2_5 MHz_High_16QAM_RB25#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:39:45

Band 2 10 MHz Low 16QAM RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:01:50

Band 2_10 MHz_Low_16QAM_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:47:42

Band 2_10 MHz_Middle_16QAM_RB50#0_1(30MHz-1GHz)




Date: 23.APR.2022 14:03:02

Band 2_10 MHz_Middle_16QAM_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:44:06

Band 2 10 MHz High 16QAM RB50#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:03:40

Band 2_10 MHz_High_16QAM_RB50#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:45:23

Band 2 15 MHz Low 16QAM RB75#0 1(30MHz-1GHz)




Date: 23.APR.2022 14:04:03

Band 2_15 MHz_Low_16QAM_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:51:28

Band 2_15 MHz_Middle_16QAM_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 14:05:18

Band 2_15 MHz_Middle_16QAM_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:48:33

Band 2_15 MHz_High_16QAM_RB75#0_1(30MHz-1GHz)




Date: 23.APR.2022 14:05:58

Band 2_15 MHz_High_16QAM_RB75#0_2(1GHz-20GHz)




Date: 23.APR.2022 13:50:23

Band 2 20 MHz Low 16QAM RB100#0 1(30MHz-1GHz)



Date: 23.APR.2022 13:58:50

Band 2_20 MHz_Low_16QAM_RB100#0_2(1GHz-20GHz)



Date: 23.APR.2022 13:55:53