



Please refer to following plots:

Band 2 1.4 MHz Low QPSK RB6#0




Date: 23.APR.2022 13:13:51

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 23.APR.2022 13:13:26

Band 2 1.4 MHz High QPSK RB6#0




Date: 23.APR.2022 13:12:17

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 23.APR.2022 13:11:55

Band 2 3 MHz Low QPSK RB15#0




Date: 23.APR.2022 13:07:42

Band 2 3 MHz Low 16QAM RB15#0




Date: 23.APR.2022 13:08:03

Band 2 3 MHz High QPSK RB15#0




Date: 23.APR.2022 13:09:38

Band 2_3 MHz_High_16QAM_RB15#0




Date: 23.APR.2022 13:09:16

Band 2 5 MHz Low QPSK RB25#0




Date: 23.APR.2022 13:03:36

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 23.APR.2022 13:03:12

Band 2 5 MHz High QPSK RB25#0




Date: 23.APR.2022 13:01:25


Band 2_5 MHz_High_16QAM_RB25#0



Date: 23.APR.2022 13:01:49




Band 2 10 MHz High QPSK RB50#0




Date: 23.APR.2022 11:57:54

Band 2 10 MHz High 16QAM RB50#0




Date: 23.APR.2022 11:58:33

Band 2 15 MHz Low QPSK RB75#0




Date: 23.APR.2022 11:53:16

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 23.APR.2022 11:53:48

Band 2 15 MHz High QPSK RB75#0




Date: 23.APR.2022 11:51:17

Band 2_15 MHz_High_16QAM_RB75#0




Date: 23.APR.2022 11:50:07

Band 2 20 MHz Low QPSK RB100#0




Date: 23.APR.2022 11:33:47

Band 2_20 MHz_Low_16QAM_RB100#0



Date: 23.APR.2022 11:35:59

Band 2 20 MHz High QPSK RB100#0




Date: 23.APR.2022 11:39:48

Band 2_20 MHz_High_16QAM_RB100#0




Date: 23.APR.2022 11:38:43

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 23.APR.2022 16:40:16

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 23.APR.2022 16:41:09

Band 4 1.4 MHz High QPSK RB6#0




Date: 23.APR.2022 16:42:43

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 23.APR.2022 16:44:45

Band 4 3 MHz Low QPSK RB15#0




Date: 23.APR.2022 16:36:09

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 23.APR.2022 16:38:14

Band 4 3 MHz High QPSK RB15#0




Date: 23.APR.2022 16:34:10

Band 4_3 MHz_High_16QAM_RB15#0




Date: 23.APR.2022 16:35:38

Band 4 5 MHz Low QPSK RB25#0




Date: 23.APR.2022 16:30:33

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 23.APR.2022 16:31:29

Band 4 5 MHz High QPSK RB25#0




Date: 23.APR.2022 16:32:45

Band 4_5 MHz_High_16QAM_RB25#0




Date: 23.APR.2022 16:33:15

Band 4 10 MHz Low QPSK RB50#0




Date: 23.APR.2022 16:27:46


Band 4_10 MHz_Low_16QAM_RB50#0



Date: 23.APR.2022 16:28:15




Date: 23.APR.2022 16:26:41




Date: 23.APR.2022 16:27:05

Band 4 15 MHz Low QPSK RB75#0




Date: 23.APR.2022 16:20:13

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 23.APR.2022 16:21:58

Band 4 15 MHz High QPSK RB75#0




Date: 23.APR.2022 16:25:59

Band 4_15 MHz_High_16QAM_RB75#0




Date: 23.APR.2022 16:24:32

Band 4 20 MHz Low QPSK RB100#0




Date: 23.APR.2022 16:16:07

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 23.APR.2022 16:17:22

Band 4 20 MHz High QPSK RB100#0




Date: 23.APR.2022 16:11:28

Band 4_20 MHz_High_16QAM_RB100#0




Date: 23.APR.2022 16:14:00

Band 5 1.4 MHz Low QPSK RB6#0




Date: 24.APR.2022 13:11:58

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 24.APR.2022 13:11:43

Band 5 1.4 MHz High QPSK RB6#0




Date: 24.APR.2022 13:10:45

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 24.APR.2022 13:10:14

Band 5 3 MHz Low QPSK RB15#0




Date: 24.APR.2022 13:15:31

Band 5 3 MHz Low 16QAM RB15#0




Date: 24.APR.2022 13:16:01

Band 5 3 MHz High QPSK RB15#0




Date: 24.APR.2022 13:14:25

Band 5_3 MHz_High_16QAM_RB15#0




Date: 24.APR.2022 13:13:59

Band 5 5 MHz Low QPSK RB25#0




Date: 24.APR.2022 13:18:50


Band 5_5 MHz_Low_16QAM_RB25#0



Date: 24.APR.2022 13:18:19




Date: 24.APR.2022 13:19:49




Date: 24.APR.2022 13:20:07

Band 5 10 MHz Low QPSK RB50#0




Date: 24.APR.2022 13:04:47

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 24.APR.2022 13:06:00

Band 5 10 MHz High QPSK RB50#0




Date: 24.APR.2022 13:07:57

Band 5_10 MHz_High_16QAM_RB50#0




Date: 24.APR.2022 13:08:41

Band 7_5 MHz_Low_QPSK_RB25#0




Date: 24.APR.2022 15:24:13

Band 7_5 MHz_Low_16QAM_RB25#0




Date: 24.APR.2022 15:23:35

Band 7 5 MHz High QPSK RB25#0




Date: 24.APR.2022 15:22:43

Band 7_5 MHz_High_16QAM_RB25#0




Date: 24.APR.2022 15:21:29

Band 7 10 MHz Low QPSK RB50#0




Date: 24.APR.2022 15:17:25

Band 7_10 MHz_Low_16QAM_RB50#0




Date: 24.APR.2022 15:11:59

Band 7 10 MHz High QPSK RB50#0




Date: 24.APR.2022 15:19:13

Band 7_10 MHz_High_16QAM_RB50#0




Date: 24.APR.2022 15:18:36

Band 7 15 MHz Low QPSK RB75#0




Date: 24.APR.2022 15:10:35


Band 7_15 MHz_Low_16QAM_RB75#0



Date: 24.APR.2022 15:09:58




Date: 24.APR.2022 15:08:46




Date: 24.APR.2022 15:07:47

Band 7 20 MHz Low QPSK RB100#0




Date: 24.APR.2022 15:03:57

Band 7_20 MHz_Low_16QAM_RB100#0




Date: 24.APR.2022 15:02:14

Band 7 20 MHz High QPSK RB100#0




Date: 24.APR.2022 15:06:02

Band 7_20 MHz_High_16QAM_RB100#0




Date: 24.APR.2022 15:05:34

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 24.APR.2022 18:28:12

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 24.APR.2022 18:30:09

Band 12 1.4 MHz High QPSK RB6#0




Date: 24.APR.2022 18:31:45

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 24.APR.2022 18:33:19

Band 12 3 MHz Low QPSK RB15#0




Date: 24.APR.2022 18:38:28

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 24.APR.2022 18:39:24

Band 12 3 MHz High QPSK RB15#0




Date: 24.APR.2022 18:37:14

Band 12_3 MHz_High_16QAM_RB15#0




Date: 24.APR.2022 18:35:55

Band 12 5 MHz Low QPSK RB25#0




Date: 24.APR.2022 18:41:58

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 24.APR.2022 18:43:47

Band 12 5 MHz High QPSK RB25#0




Date: 24.APR.2022 18:45:32

Band 12_5 MHz_High_16QAM_RB25#0




Date: 24.APR.2022 18:48:02

Band 12 10 MHz Low QPSK RB50#0




Date: 24.APR.2022 18:53:57


Band 12_10 MHz_Low_16QAM_RB50#0





Date: 24.APR.2022 18:54:17




Date: 24.APR.2022 18:52:16



Date: 24.APR.2022 18:49:34




Band 17 5 MHz High QPSK RB25#0



Date: 23.APR.2022 18:55:18

Band 17_5 MHz_High_16QAM_RB25#0



Date: 23.APR.2022 18:54:57