





NTNV-11AC20SISO-Ant1-5240




NTNV-11AC20SISO-Ant1-5745

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


Appendix C: Maximum conducted output power

Test Result Channel Power

Test Mode	Antenna	Frequency [MHz]	Channel Power [dBm]	Duty Cycle [%]	DC Factor [dB]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	5180	13.72	72.40	1.40	15.12	≤23.98	PASS
11A	Ant1	5200	13.40	73.68	1.33	14.73	≤23.98	PASS
11A	Ant1	5240	13.10	72.40	1.40	14.50	≤23.98	PASS
11A	Ant1	5745	11.40	72.02	1.43	12.83	≤30.00	PASS
11A	Ant1	5785	11.28	73.68	1.33	12.61	≤30.00	PASS
11A	Ant1	5825	11.43	72.77	1.38	12.81	≤30.00	PASS
11N20SISO	Ant1	5180	13.49	71.43	1.46	14.95	≤23.98	PASS
11N20SISO	Ant1	5200	13.21	70.81	1.50	14.71	≤23.98	PASS
11N20SISO	Ant1	5240	12.91	71.98	1.43	14.34	≤23.98	PASS
11N20SISO	Ant1	5745	10.74	70.65	1.51	12.25	≤30.00	PASS
11N20SISO	Ant1	5785	10.61	71.43	1.46	12.07	≤30.00	PASS
11N20SISO	Ant1	5825	10.16	71.43	1.46	11.62	≤30.00	PASS
11N40SISO	Ant1	5190	12.43	55.17	2.58	15.01	≤23.98	PASS
11N40SISO	Ant1	5230	12.15	55.56	2.55	14.70	≤23.98	PASS
11N40SISO	Ant1	5755	9.57	55.17	2.58	12.15	≤30.00	PASS
11N40SISO	Ant1	5795	9.63	55.17	2.58	12.21	≤30.00	PASS
11AC20SISO	Ant1	5180	13.37	71.58	1.45	14.82	≤23.98	PASS
11AC20SISO	Ant1	5200	13.11	70.81	1.50	14.61	≤23.98	PASS
11AC20SISO	Ant1	5240	12.89	71.58	1.45	14.34	≤23.98	PASS
11AC20SISO	Ant1	5745	10.64	71.20	1.48	12.12	≤30.00	PASS
11AC20SISO	Ant1	5785	10.56	71.58	1.45	12.01	≤30.00	PASS
11AC20SISO	Ant1	5825	10.59	71.58	1.45	12.04	≤30.00	PASS
11AC40SISO	Ant1	5190	12.41	55.56	2.55	14.96	≤23.98	PASS
11AC40SISO	Ant1	5230	12.07	56.03	2.52	14.59	≤23.98	PASS
11AC40SISO	Ant1	5755	9.54	55.08	2.59	12.13	≤30.00	PASS
11AC40SISO	Ant1	5795	9.58	55.93	2.52	12.10	≤30.00	PASS
11AC80SISO	Ant1	5210	11.14	44.44	3.52	14.66	≤23.98	PASS
11AC80SISO	Ant1	5775	8.34	43.84	3.58	11.92	≤30.00	PASS

Note: The cable loss are compensated in the graph.


Test Graphs Channel Power



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix D: Maximum power spectral density

Test Result-B1

TestMode	Antenna	Frequency [MHz]	Reading Result [dBm/MHz]	DC Factor [dB]	Result [dBm/MHz]	Limit [dBm/MHz]	Verdict
11A	Ant1	5180	4.27	1.4	5.67	≤11.00	PASS
11A	Ant1	5200	3.79	1.4	5.19	≤11.00	PASS
11A	Ant1	5240	3.30	1.4	4.70	≤11.00	PASS
11N20SISO	Ant1	5180	3.33	1.46	4.79	≤11.00	PASS
11N20SISO	Ant1	5200	3.17	1.5	4.67	≤11.00	PASS
11N20SISO	Ant1	5240	3.03	1.43	4.46	≤11.00	PASS
11N40SISO	Ant1	5190	-0.38	2.58	2.20	≤11.00	PASS
11N40SISO	Ant1	5230	-0.34	2.55	2.21	≤11.00	PASS
11AC20SISO	Ant1	5180	3.08	1.48	4.56	≤11.00	PASS
11AC20SISO	Ant1	5200	2.69	1.5	4.19	≤11.00	PASS
11AC20SISO	Ant1	5240	3.00	1.45	4.45	≤11.00	PASS
11AC40SISO	Ant1	5190	-0.58	2.59	2.01	≤11.00	PASS
11AC40SISO	Ant1	5230	-1.68	2.52	0.84	≤11.00	PASS
11AC80SISO	Ant1	5210	-5.76	3.52	-2.24	≤11.00	PASS


Note: The cable loss are compensated in the graph.

Test Result-B4

TestMode	Antenna	Frequency [MHz]	Reading Result [dBm/500KHz]	DC Factor [dB]	Result [dBm/500KHz]	Limit [dBm/500KHz]	Verdict
11A	Ant1	5745	-1.24	1.43	0.19	≤30.00	PASS
11A	Ant1	5785	-1.32	1.4	0.08	≤30.00	PASS
11A	Ant1	5825	-1.84	1.38	-0.46	≤30.00	PASS
11N20SISO	Ant1	5745	-2.47	1.51	-0.96	≤30.00	PASS
11N20SISO	Ant1	5785	-2.02	1.53	-0.49	≤30.00	PASS
11N20SISO	Ant1	5825	-2.40	1.46	-0.94	≤30.00	PASS
11N40SISO	Ant1	5755	-6.16	2.58	-3.58	≤30.00	PASS
11N40SISO	Ant1	5795	-5.86	2.58	-3.28	≤30.00	PASS
11AC20SISO	Ant1	5745	-2.44	1.48	-0.96	≤30.00	PASS
11AC20SISO	Ant1	5785	-2.60	1.45	-1.15	≤30.00	PASS
11AC20SISO	Ant1	5825	-2.92	1.45	-1.47	≤30.00	PASS
11AC40SISO	Ant1	5755	-6.42	2.59	-3.83	≤30.00	PASS
11AC40SISO	Ant1	5795	-6.09	2.52	-3.57	≤30.00	PASS
11AC80SISO	Ant1	5775	-11.33	3.58	-7.75	≤30.00	PASS

Note: The cable loss are compensated in the graph.


Test Graphs



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5785-PASS





11A-Ant1-5825-PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





11N20SISO-Ant1-5240-PASS




11N20SISO-Ant1-5745-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20SISO-Ant1-5785-PASS




11N20SISO-Ant1-5825-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N40SISO-Ant1-5755-PASS




11N40SISO-Ant1-5795-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5180-PASS




11AC20SISO-Ant1-5200-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11AC20SISO-Ant1-5240-PASS



11AC20SISO-Ant1-5745-PASS



11AC20SISO-Ant1-5785-PASS




11AC20SISO-Ant1-5825-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC40SISO-Ant1-5755-PASS




11AC40SISO-Ant1-5795-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC80SISO-Ant1-5210-PASS



11AC80SISO-Ant1-5775-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix E: Band edge measurements

Test Result B1

TestMode	Antenna	ChName	Frequency[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5180	-37.88	≤-27	PASS
11A	Ant1	High	5240	-49.4	≤-27	PASS
11N20SISO	Ant1	Low	5180	-33.59	≤-27	PASS
11N20SISO	Ant1	High	5240	-48.74	≤-27	PASS
11N40SISO	Ant1	Low	5190	-27.11	≤-27	PASS
11N40SISO	Ant1	High	5230	-47.72	≤-27	PASS
11AC20SISO	Ant1	Low	5180	-31.14	≤-27	PASS
11AC20SISO	Ant1	High	5240	-49.52	≤-27	PASS
11AC40SISO	Ant1	Low	5190	-28.59	≤-27	PASS
11AC40SISO	Ant1	High	5230	-49.38	≤-27	PASS
11AC80SISO	Ant1	High	5210	-48.5	≤-27	PASS
11AC80SISO	Ant1	Low	5210	-35.46	≤-27	PASS

Note: The margin is at least greater than the antenna gain plus the cable loss.

Test Result B4

TestMode	Antenna	ChName	Frequency[MHz]	FreqRange[MHz]	Result[dBm]	Limit[dBm]	Verdict
11A	Ant1	Low	5745	5720~5725	-43.23	≤15.98	PASS
11A	Ant1	Low	5745	5700~5720	-41.41	≤15.37	PASS
11A	Ant1	Low	5745	5650~5700	-49.88	≤-26.88	PASS
11A	Ant1	Low	5745	5760~5650	-49.39	≤-27	PASS
11A	Ant1	High	5825	5850~5855	-41.88	≤16.54	PASS
11A	Ant1	High	5825	5855~5875	-42.21	≤15.33	PASS
11A	Ant1	High	5825	5875~5925	-48.68	≤-25.13	PASS
11A	Ant1	High	5825	5925~5935	-49.08	≤-27	PASS
11N20SISO	Ant1	Low	5745	5720~5725	-43.97	≤15.98	PASS
11N20SISO	Ant1	Low	5745	5700~5720	-47.71	≤10.05	PASS
11N20SISO	Ant1	Low	5745	5650~5700	-51.15	≤-26.38	PASS
11N20SISO	Ant1	Low	5745	5760~5650	-50.18	≤-27	PASS
11N20SISO	Ant1	High	5825	5850~5855	-46.47	≤16.10	PASS
11N20SISO	Ant1	High	5825	5855~5875	-48.94	≤10.29	PASS
11N20SISO	Ant1	High	5825	5875~5925	-48.15	≤-26.73	PASS
11N20SISO	Ant1	High	5825	5925~5935	-49.04	≤-27	PASS
11N40SISO	Ant1	Low	5755	5720~5725	-42.42	≤15.90	PASS
11N40SISO	Ant1	Low	5755	5700~5720	-32.48	≤12.79	PASS
11N40SISO	Ant1	Low	5755	5650~5700	-47.91	≤-26.50	PASS
11N40SISO	Ant1	Low	5755	5780~5650	-49.35	≤-27	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

11N40SISO	Ant1	High	5795	5850~5855	-48.02	≤15.85	PASS
11N40SISO	Ant1	High	5795	5855~5875	-41.66	≤10.88	PASS
11N40SISO	Ant1	High	5795	5875~5925	-50.76	≤-26.97	PASS
11N40SISO	Ant1	High	5795	5925~5935	-49.74	≤-27	PASS
11AC20SISO	Ant1	Low	5745	5720~5725	-44.64	≤15.98	PASS
11AC20SISO	Ant1	Low	5745	5700~5720	-47.73	≤10.61	PASS
11AC20SISO	Ant1	Low	5745	5650~5700	-50.77	≤-26.88	PASS
11AC20SISO	Ant1	Low	5745	5760~5650	-50.57	≤-27	PASS
11AC20SISO	Ant1	High	5825	5850~5855	-48.48	≤15.65	PASS
11AC20SISO	Ant1	High	5825	5855~5875	-48.03	≤10.13	PASS
11AC20SISO	Ant1	High	5825	5875~5925	-50.43	≤-26.58	PASS
11AC20SISO	Ant1	High	5825	5925~5935	-49.93	≤-27	PASS
11AC40SISO	Ant1	Low	5755	5720~5725	-40.67	≤16.79	PASS
11AC40SISO	Ant1	Low	5755	5700~5720	-43.32	≤12.90	PASS
11AC40SISO	Ant1	Low	5755	5650~5700	-49.78	≤-26.94	PASS
11AC40SISO	Ant1	Low	5755	5780~5650	-49.8	≤-27	PASS
11AC40SISO	Ant1	High	5795	5850~5855	-49.18	≤15.85	PASS
11AC40SISO	Ant1	High	5795	5855~5875	-48.09	≤10.27	PASS
11AC40SISO	Ant1	High	5795	5875~5925	-50.91	≤-26.26	PASS
11AC40SISO	Ant1	High	5795	5925~5935	-50.23	≤-27	PASS
11AC80SISO	Ant1	Low	5775	5720~5725	-36.66	≤16.69	PASS
11AC80SISO	Ant1	Low	5775	5700~5720	-37.36	≤11.52	PASS
11AC80SISO	Ant1	Low	5775	5650~5700	-47.79	≤-25.55	PASS
11AC80SISO	Ant1	Low	5775	5800~5650	-48.36	≤-27	PASS
11AC80SISO	Ant1	High	5775	5850~5855	-37.52	≤15.98	PASS
11AC80SISO	Ant1	High	5775	5855~5875	-38.4	≤11.82	PASS
11AC80SISO	Ant1	High	5775	5875~5925	-53.19	≤-26.46	PASS
11AC80SISO	Ant1	High	5775	5925~5935	-51.39	≤-27	PASS

Note: The margin is at least greater than the antenna gain plus the cable loss.


Test Graphs B1



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11AC20SISO-Ant1-5180-PASS




11AC20SISO-Ant1-5240-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com


Test Graphs B4




Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.


Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com




11N20SISO-Ant1-5745-PASS



11N20SISO-Ant1-5825-PASS







Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com





11AC80SISO-Ant1-5775-PASS



11AC80SISO-Ant1-5775-PASS

---END---