

Appendix C – SAR Test Setup Photos



Test Position Front 0 mm Gap

Note: Cables are required during use.



Test Position Back 0 mm Gap

Note: Cables are required during use.



Test Position Left 0 mm Gap

Note: Cables are required during use.



Front of Device



Back of Device