





NTNV-11N20MIMO-Ant1-5240




NTNV-11N20MIMO-Ant2-5240


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N20MIMO-Ant1-5260




NTNV-11N20MIMO-Ant2-5260


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N20MIMO-Ant1-5300




NTNV-11N20MIMO-Ant2-5300


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N20MIMO-Ant1-5320




NTNV-11N20MIMO-Ant2-5320


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N40MIMO-Ant1-5190




NTNV-11N40MIMO-Ant2-5190


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N40MIMO-Ant1-5230




NTNV-11N40MIMO-Ant2-5230


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N40MIMO-Ant1-5270




NTNV-11N40MIMO-Ant2-5270


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11N40MIMO-Ant1-5310




NTNV-11N40MIMO-Ant2-5310


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5180




NTNV-11AC20MIMO-Ant2-5180


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5220




NTNV-11AC20MIMO-Ant2-5220


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5240




NTNV-11AC20MIMO-Ant2-5240


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5260




NTNV-11AC20MIMO-Ant2-5260


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5300




NTNV-11AC20MIMO-Ant2-5300


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC20MIMO-Ant1-5320




NTNV-11AC20MIMO-Ant2-5320


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40MIMO-Ant2-5190




NTNV-11AC40MIMO-Ant1-5190


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40MIMO-Ant1-5230




NTNV-11AC40MIMO-Ant2-5230


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40MIMO-Ant1-5270




NTNV-11AC40MIMO-Ant2-5270


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC40MIMO-Ant1-5310




NTNV-11AC40MIMO-Ant2-5310


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC80MIMO-Ant1-5210




NTNV-11AC80MIMO-Ant2-5210


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AC80MIMO-Ant1-5290




NTNV-11AC80MIMO-Ant2-5290


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant1-5180




NTNV-11AX20MIMO-Ant2-5180


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant1-5220




NTNV-11AX20MIMO-Ant2-5220


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant1-5240




NTNV-11AX20MIMO-Ant2-5240


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant1-5260




NTNV-11AX20MIMO-Ant2-5260


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant1-5300




NTNV-11AX20MIMO-Ant2-5300


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX20MIMO-Ant2-5320




NTNV-11AX20MIMO-Ant1-5320


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX40MIMO-Ant1-5190




NTNV-11AX40MIMO-Ant2-5190


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX40MIMO-Ant1-5230




NTNV-11AX40MIMO-Ant2-5230


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX40MIMO-Ant1-5270




NTNV-11AX40MIMO-Ant2-5270


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX40MIMO-Ant1-5310




NTNV-11AX40MIMO-Ant2-5310


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX80MIMO-Ant1-5210




NTNV-11AX80MIMO-Ant2-5210


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



NTNV-11AX80MIMO-Ant1-5290



NTNV-11AX80MIMO-Ant2-5290

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com

Appendix C: Maximum Conducted Output Power

Test Result Channel Power

Test Mode	Antenna	Frequency [MHz]	Result [dBm]	Limit [dBm]	Verdict
11A	Ant1	5180	14.02	≤23.98	PASS
11A	Ant2	5180	13.92	≤23.98	PASS
11A	Ant1	5220	14.83	≤23.98	PASS
11A	Ant2	5220	14.69	≤23.98	PASS
11A	Ant1	5240	15.02	≤23.98	PASS
11A	Ant2	5240	15.10	≤23.98	PASS
11A	Ant1	5260	14.33	≤23.98	PASS
11A	Ant2	5260	14.48	≤23.98	PASS
11A	Ant1	5300	15.04	≤23.98	PASS
11A	Ant2	5300	15.10	≤23.98	PASS
11A	Ant1	5320	15.35	≤23.98	PASS
11A	Ant2	5320	14.41	≤23.98	PASS
11N20MIMO	Ant1	5180	13.04	≤23.98	PASS
11N20MIMO	Ant2	5180	13.02	≤23.98	PASS
11N20MIMO	total	5180	16.04	≤23.98	PASS
11N20MIMO	Ant1	5220	13.74	≤23.98	PASS
11N20MIMO	Ant2	5220	13.69	≤23.98	PASS
11N20MIMO	total	5220	16.73	≤23.98	PASS
11N20MIMO	Ant1	5240	14.18	≤23.98	PASS
11N20MIMO	Ant2	5240	14.07	≤23.98	PASS
11N20MIMO	total	5240	17.14	≤23.98	PASS
11N20MIMO	Ant1	5260	14.57	≤23.98	PASS
11N20MIMO	Ant2	5260	14.55	≤23.98	PASS
11N20MIMO	total	5260	17.57	≤23.98	PASS
11N20MIMO	Ant1	5300	15.02	≤23.98	PASS
11N20MIMO	Ant2	5300	15.04	≤23.98	PASS
11N20MIMO	total	5300	18.04	≤23.98	PASS
11N20MIMO	Ant1	5320	14.38	≤23.98	PASS
11N20MIMO	Ant2	5320	14.43	≤23.98	PASS
11N20MIMO	total	5320	17.42	≤23.98	PASS
11N40MIMO	Ant1	5190	12.73	≤23.98	PASS
11N40MIMO	Ant2	5190	12.77	≤23.98	PASS
11N40MIMO	total	5190	15.76	≤23.98	PASS
11N40MIMO	Ant1	5230	13.46	≤23.98	PASS
11N40MIMO	Ant2	5230	13.53	≤23.98	PASS
11N40MIMO	total	5230	16.51	≤23.98	PASS
11N40MIMO	Ant1	5270	14.28	≤23.98	PASS

11N40MIMO	Ant2	5270	14.27	≤23.98	PASS
11N40MIMO	total	5270	17.29	≤23.98	PASS
11N40MIMO	Ant1	5310	14.81	≤23.98	PASS
11N40MIMO	Ant2	5310	14.82	≤23.98	PASS
11N40MIMO	total	5310	17.83	≤23.98	PASS
11AC20MIMO	Ant1	5180	13.07	≤23.98	PASS
11AC20MIMO	Ant2	5180	13.12	≤23.98	PASS
11AC20MIMO	total	5180	16.11	≤23.98	PASS
11AC20MIMO	Ant1	5220	13.77	≤23.98	PASS
11AC20MIMO	Ant2	5220	13.64	≤23.98	PASS
11AC20MIMO	total	5220	16.72	≤23.98	PASS
11AC20MIMO	Ant1	5240	14.17	≤23.98	PASS
11AC20MIMO	Ant2	5240	14.13	≤23.98	PASS
11AC20MIMO	total	5240	17.16	≤23.98	PASS
11AC20MIMO	Ant1	5260	14.60	≤23.98	PASS
11AC20MIMO	Ant2	5260	14.52	≤23.98	PASS
11AC20MIMO	total	5260	17.57	≤23.98	PASS
11AC20MIMO	Ant1	5300	15.13	≤23.98	PASS
11AC20MIMO	Ant2	5300	15.10	≤23.98	PASS
11AC20MIMO	total	5300	18.13	≤23.98	PASS
11AC20MIMO	Ant1	5320	14.27	≤23.98	PASS
11AC20MIMO	Ant2	5320	14.30	≤23.98	PASS
11AC20MIMO	total	5320	17.30	≤23.98	PASS
11AC40MIMO	Ant1	5190	13.70	≤23.98	PASS
11AC40MIMO	Ant2	5190	13.78	≤23.98	PASS
11AC40MIMO	total	5190	16.75	≤23.98	PASS
11AC40MIMO	Ant1	5230	14.42	≤23.98	PASS
11AC40MIMO	Ant2	5230	14.43	≤23.98	PASS
11AC40MIMO	total	5230	17.44	≤23.98	PASS
11AC40MIMO	Ant1	5270	14.22	≤23.98	PASS
11AC40MIMO	Ant2	5270	14.21	≤23.98	PASS
11AC40MIMO	total	5270	17.23	≤23.98	PASS
11AC40MIMO	Ant1	5310	14.85	≤23.98	PASS
11AC40MIMO	Ant2	5310	14.81	≤23.98	PASS
11AC40MIMO	total	5310	17.84	≤23.98	PASS
11AC80MIMO	Ant1	5210	13.85	≤23.98	PASS
11AC80MIMO	Ant2	5210	13.87	≤23.98	PASS
11AC80MIMO	total	5210	16.87	≤23.98	PASS
11AC80MIMO	Ant1	5290	14.28	≤23.98	PASS
11AC80MIMO	Ant2	5290	14.24	≤23.98	PASS
11AC80MIMO	total	5290	17.27	≤23.98	PASS
11AX20MIMO	Ant1	5180	14.86	≤23.98	PASS

Shenzhen Anbotek Compliance Laboratory Limited


Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com


11AX20MIMO	Ant2	5180	14.82	≤23.98	PASS
11AX20MIMO	total	5180	17.85	≤23.98	PASS
11AX20MIMO	Ant1	5220	14.55	≤23.98	PASS
11AX20MIMO	Ant2	5220	14.64	≤23.98	PASS
11AX20MIMO	total	5220	17.61	≤23.98	PASS
11AX20MIMO	Ant1	5240	14.93	≤23.98	PASS
11AX20MIMO	Ant2	5240	14.85	≤23.98	PASS
11AX20MIMO	total	5240	17.90	≤23.98	PASS
11AX20MIMO	Ant1	5260	15.14	≤23.98	PASS
11AX20MIMO	Ant2	5260	15.22	≤23.98	PASS
11AX20MIMO	total	5260	18.19	≤23.98	PASS
11AX20MIMO	Ant1	5300	14.68	≤23.98	PASS
11AX20MIMO	Ant2	5300	14.71	≤23.98	PASS
11AX20MIMO	total	5300	17.71	≤23.98	PASS
11AX20MIMO	Ant1	5320	13.78	≤23.98	PASS
11AX20MIMO	Ant2	5320	13.76	≤23.98	PASS
11AX20MIMO	total	5320	16.78	≤23.98	PASS
11AX40MIMO	Ant1	5190	14.29	≤23.98	PASS
11AX40MIMO	Ant2	5190	14.28	≤23.98	PASS
11AX40MIMO	total	5190	17.30	≤23.98	PASS
11AX40MIMO	Ant1	5230	14.95	≤23.98	PASS
11AX40MIMO	Ant2	5230	14.98	≤23.98	PASS
11AX40MIMO	total	5230	17.98	≤23.98	PASS
11AX40MIMO	Ant1	5270	13.72	≤23.98	PASS
11AX40MIMO	Ant2	5270	13.72	≤23.98	PASS
11AX40MIMO	total	5270	16.73	≤23.98	PASS
11AX40MIMO	Ant1	5310	14.40	≤23.98	PASS
11AX40MIMO	Ant2	5310	14.38	≤23.98	PASS
11AX40MIMO	total	5310	17.40	≤23.98	PASS
11AX80MIMO	Ant1	5210	13.26	≤23.98	PASS
11AX80MIMO	Ant2	5210	13.20	≤23.98	PASS
11AX80MIMO	total	5210	16.24	≤23.98	PASS
11AX80MIMO	Ant1	5290	13.86	≤23.98	PASS
11AX80MIMO	Ant2	5290	13.86	≤23.98	PASS
11AX80MIMO	total	5290	16.87	≤23.98	PASS

Note: 1.The cable loss are compensated in the graph.

Test Graphs Channel Power



11A-Ant1-5180-PASS




11A-Ant2-5180-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5220-PASS




11A-Ant2-5220-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5240-PASS




11A-Ant2-5240-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5260-PASS




11A-Ant2-5260-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5300-PASS




11A-Ant2-5300-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11A-Ant1-5320-PASS




11A-Ant2-5320-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5180-PASS




11N20MIMO-Ant2-5180-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5220-PASS




11N20MIMO-Ant2-5220-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5240-PASS




11N20MIMO-Ant2-5240-PASS


Shenzhen Anbotech Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotech.com E-mail: service@anbotech.com



11N20MIMO-Ant1-5260-PASS




11N20MIMO-Ant2-5260-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5300-PASS




11N20MIMO-Ant2-5300-PASS


Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com



11N20MIMO-Ant1-5320-PASS



11N20MIMO-Ant2-5320-PASS

Shenzhen Anbotek Compliance Laboratory Limited

Any unauthorized modification, forgery, or falsification of this document constitutes a violation of law and is subject to legal penalties. If you have any questions, you may scan the QR code to download the report for verification or contact us via email.

Hotline: 400-003-0500 web: www.anbotek.com E-mail: service@anbotek.com