




EUT Mode


802.11ax HE20 52RU38

Plot on 6195 MHz




05:04:05 PM 11/14/2025

Plot on 6475 MHz




08:30:47 AM 11/15/2025

Plot on 6695 MHz



09:43:18 AM 11/15/2025

Plot on 6995 MHz




10:54:21 AM 11/15/2025



EUT Mode


802.11ax HE20 52RU40

Plot on 6415 MHz




05:35:30 PM 11/14/2025

Plot on 6515 MHz




08:54:43 AM 11/15/2025

Plot on 6875 MHz



09:56:31 AM 11/15/2025

Plot on 7095 MHz




11:04:33 AM 11/15/2025



EUT Mode


802.11ax HE20 106RU53

Plot on 5955 MHz




04:41:00 PM 11/14/2025

Plot on 6195 MHz




05:13:36 PM 11/14/2025

Plot on 6435 MHz



06:02:00 PM 11/14/2025


Plot on 6475 MHz




08:32:52 AM 11/15/2025




Plot on 6535 MHz




Plot on 6695 MHz



Plot on 6895 MHz



Plot on 6995 MHz






EUT Mode


802.11ax HE20 106RU54

Plot on 6415 MHz




05:50:14 PM 11/14/2025

Plot on 6515 MHz




08:59:53 AM 11/15/2025

Plot on 6875 MHz



09:58:40 AM 11/15/2025

Plot on 7095 MHz




11:02:13 AM 11/15/2025




EUT Mode

802.11ax HE20 242RU61


Plot on 5955 MHz




Plot on 6195 MHz



Plot on 6415 MHz




Plot on 6435 MHz






Plot on 6475 MHz




08:40:42 AM 11/15/2025

Plot on 6515 MHz




08:45:32 AM 11/15/2025

Plot on 6535 MHz




09:32:09 AM 11/15/2025

Plot on 6695 MHz




09:46:50 AM 11/15/2025

Plot on 6875 MHz



10:00:52 AM 11/15/2025


Plot on 6895 MHz



10:03:57 AM 11/15/2025




Plot on 6995 MHz



10:58:14 AM 11/15/2025

Plot on 7095 MHz




11:00:18 AM 11/15/2025




EUT Mode

802.11ax HE40 Full RU


Plot on 5965 MHz




Plot on 6205 MHz



Plot on 6405 MHz




Plot on 6445 MHz






Plot on 6485 MHz




03:43:20 PM 10/28/2025

Plot on 6525 MHz




03:48:58 PM 10/28/2025

Plot on 6565 MHz




04:00:51 PM 10/28/2025

Plot on 6685 MHz




04:09:14 PM 10/28/2025

Plot on 6885 MHz



04:41:28 PM 10/28/2025


Plot on 6925 MHz




04:44:36 PM 10/28/2025



Plot on 7005 MHz



Plot on 7085 MHz






EUT Mode


802.11ax HE40 484RU65

Plot on 5965 MHz




04:29:52 PM 10/29/2025

Plot on 6205 MHz




04:32:11 PM 10/29/2025

Plot on 6405 MHz



04:36:18 PM 10/29/2025


Plot on 6445 MHz



04:38:52 PM 10/29/2025




Plot on 6485 MHz




05:12:50 PM 10/29/2025

Plot on 6525 MHz




05:09:21 PM 10/29/2025

Plot on 6565 MHz




05:18:01 PM 10/29/2025

Plot on 6685 MHz




05:30:55 PM 10/29/2025

Plot on 6885 MHz



05:33:59 PM 10/29/2025


Plot on 6925 MHz



10:29:42 AM 10/30/2025



Plot on 7005 MHz



Plot on 7085 MHz

