

Audit Mode Request Letter
For Certification Service in the USA

Federal Communications Commission

Equipment Authorization Division, Application Processing Branch
7435 Oakland Mills Road
Columbia, MD 21048

To whom it may concern

The company as listed hereby requests to supersede the exhibits listed in the table below from the application with the FCC ID as listed after the 30 days period.

MODEL NUMBER: SB26BTXRGB
(MODEL NUMBER OF UNIT TESTED)
FCC ID: 2AYOQ-SB26BTXRGB
Granted on: SB26BTXRGB
Company Name: SPIRIT LLC
Address: 1400 NW 159TH ST,BAY 101 MIAMI
GARDENS, FL 33169MIAMI, Florida, 33169
United States


Phone: 9545920227

The Reason for the supersede are as follows:

Exhibit type	Reason for supersede
LCSA03194025EA_FCC Report_BT	The product name is incorrect and needs to be modified
Appendix A Test Data for BT FCC ID	The product name is incorrect and needs to be modified
RF Exposure Evaluation_FCC	The product name is incorrect and needs to be modified
Operation Description	The product name is incorrect and needs to be modified
Label and Location	The product name is incorrect and needs to be modified

New exhibits will be uploaded to the application once the audit mode is active,

Sincerely,


Signature
Printed Name

04 / 19 / 2024

Date

Job Title

General Manager

Company SPIRIT LLC

Address 1400 NW 159TH ST BAY 101 MIAMI
GARDENS, FL 33169 MIAMI Contact
FLORIDA 33169 United States

Phone 9545920227

Email a@ds18.com