


TEST SETUP PHOTOS

1 Radiated Field Strength Measurement


Below 1 GHz



Close-up Photo



Above 1 GHz



Below 1 GHz, The USB Test Mode





Close-up Photo, The USB Test Mode



Above 1 GHz, The USB Test Mode



2 Conducted Emission



The USB Test Mode



The USB Test Mode

