




A

The drawing shows a circular component with a central hole. The outer ring is filled with a cross-hatched pattern. A vertical centerline is shown. A cross-section is indicated by a dashed line. The cross-section shows a central shaft with a keyway, a hatched area representing a different material, and a flange. A detail view of the flange is shown to the right, with a dashed line indicating the section line.

ISSUE



FILE NAME	7666-E-833
-----------	------------

8