



(7/14/2023)

Thunder Software Technology Co., Ltd.
ThunderSoft Building, Building 3, No.9 Qinghua Dong Road,
Haidian District, Beijing, China,100083

Reply: Antenna permanently glued with epoxy to a SMA connector for (FCC ID: 2BA4NTX11010401)

[Thunder Software Technology Co., Ltd.] ("the applicant") certifies that the antenna permanently glued with epoxy to a SMA connector to 353028 D01 Antennas Part 15 Transmitters v01r01 of the FCC rules.

Sincerely,

A handwritten signature in black ink, appearing to read "Chen Yang", enclosed within a light gray rectangular box.

(
(Chen Yang)